

**Aviation Safety Investigation Report
198803788**

**Boeing 767
McDonnell Douglas DC9
British Aerospace 125**

10 August 1988

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198803788
Location: Brisbane QLD
Date: 10 August 1988
Highest Injury Level: Nil
Injuries:

Occurrence Type: Incident

Time: 1705

	Fatal	Serious	Minor	None
Crew	0	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	0

Aircraft Details: Boeing 767	McDonnell Douglas DC9	British Aerospace 125
Registration: VH-RMG	VH-TJQ	VH-HSS
Serial Number:		
Operation Type: Regular Public Transport	Regular Public Transport	Private
Damage Level: Nil	Nil	Nil
Departure Point: N/A	N/A	
Departure Time: N/A		
Destination: N/A		

Approved for Release: 31 October 1988

Circumstances:

VH-RMG was cleared to land on runway 19. VH-HSS was cleared to line up after VH-RMG had landed and told to expect an immediate takeoff clearance. At about this time VH-TJQ was approaching final and about 12 kilometres from the runway. At the end of its landing roll VH-RMG turned into a highspeed exit and stopped with the rear of the aircraft over the runway and with the entire aircraft infringing the flight strip. The radio transmitter of VH-RMG then started to operate continuously thus preventing effective communication between the Tower and any aircraft. The crew of VH-RMG attempted to call on the Surface Movement Control(SMC) frequency but the transmitter continued to operate continuously. At the same time the pilot of VH-TJQ was attempting to ascertain from the Tower if his aircraft was cleared to land. He also called on the SMC frequency but that frequency was jammed at that time by the continuous transmissions from VH-RMG. By this stage the pilot of VH-TJQ had decided to land if they did not obtain a landing clearance. When the aircraft was at about 200 feet above ground level the crew noticed that VH-HSS was lined up on the threshold of the runway. An immediate go-around was carried out. The rear section of VH-RMG still infringed the runway. During the above sequence the Tower Controller had been attempting in vain to both instruct VH-TJQ to carry out a go-around and to have VH-HSS vacate the runway. Neither aircraft had received these instructions because of the continuous transmissions from VH-RMG. The sighting of VH-HSS on the runway threshold was made more difficult for the crew of VH-TJQ by the fading light and the fact that the white aircraft was aligned with the white threshold markings. Subsequent checks of the radio systems in VH-RMG failed to find any faults with the systems.

Significant Factors:

The following factors were considered relevant to the development of the incident

1. Pilot of VH-RMG did not vacate runway in a timely manner.
2. Continuous radio transmission from VH-RMG precluded communications.
3. Pilot of VH-TJQ intended landing without clearance.
4. Prevailing light conditions and the lack of contrast between the threshold markings and Vh-HSS made it difficult to sight the aircraft when it was lined up for takeoff.