



Australian Government

Australian Transport Safety Bureau

Descent below minimum altitude involving a Boeing 777, A6-ECO

near Melbourne, Victoria, 18 July 2014

ATSB Transport Safety Report
Aviation Occurrence Investigation
AO-2014-128
Final – 7 October 2015

Released in accordance with section 25 of the *Transport Safety Investigation Act 2003*

Publishing information

Published by: Australian Transport Safety Bureau
Postal address: PO Box 967, Civic Square ACT 2608
Office: 62 Northbourne Avenue Canberra, Australian Capital Territory 2601
Telephone: 1800 020 616, from overseas +61 2 6257 4150 (24 hours)
Accident and incident notification: 1800 011 034 (24 hours)
Facsimile: 02 6247 3117, from overseas +61 2 6247 3117
Email: atsbinfo@atsb.gov.au
Internet: www.atsb.gov.au

© Commonwealth of Australia 2015



Ownership of intellectual property rights in this publication

Unless otherwise noted, copyright (and any other intellectual property rights, if any) in this publication is owned by the Commonwealth of Australia.

Creative Commons licence

With the exception of the Coat of Arms, ATSB logo, and photos and graphics in which a third party holds copyright, this publication is licensed under a Creative Commons Attribution 3.0 Australia licence.

Creative Commons Attribution 3.0 Australia Licence is a standard form license agreement that allows you to copy, distribute, transmit and adapt this publication provided that you attribute the work.

The ATSB's preference is that you attribute this publication (and any material sourced from it) using the following wording: *Source:* Australian Transport Safety Bureau

Copyright in material obtained from other agencies, private individuals or organisations, belongs to those agencies, individuals or organisations. Where you want to use their material you will need to contact them directly.

Addendum

Page	Change	Date


Descent below minimum altitude involving a Boeing 777, A6-ECO

What happened

On the morning of 18 July 2014, a Boeing 777 operated by Emirates Airlines, registered A6-ECO, was on descent into Melbourne, Victoria via an ARBEY 4U Standard Arrival Route (STAR)¹ for the Area Navigation U (RNAV-U) Required Navigation Performance (RNP) runway 16 approach. There was some cloud and showers in the area at the time, with the wind from the south-west.

The ARBEY 4U STAR required that the aircraft track from ARBEY to BUNKY, then to the Bolinda (BOL) non-directional (radio) beacon (NDB).² The arrival procedure included speed and altitude restrictions at BUNKY, and a speed restriction at BOL, but there was no altitude restriction at BOL depicted on the STAR chart. Even though there was no altitude restriction depicted at BOL, the STAR chart depicted a minimum en route altitude (MEA) of 3,400 ft and a minimum terrain clearance altitude (MTCA) of 3,700 ft, between BUNKY and BOL (Figure 1).³

Figure 1: Excerpt from the ARBEY 4 STAR chart used by the operator depicting MEA (3400) and MTCA (3700)



Source: Aircraft operator – image cropped by the ATSB

The ARBEY 4U STAR linked to the RNAV-U (RNP) runway 16 approach at BOL, which was identified as the initial approach fix for the RNAV-U (RNP) runway 16 approach. While no altitude was specified at BOL on the STAR chart, the RNAV-U (RNP) runway 16 approach chart depicted two altitudes at BOL (Figure 2). These were:


- an 'at or above' 4,000 ft altitude restriction at BOL when joining the approach from the ARBEY STAR
- an 'at or above' 3,000 ft altitude restriction at BOL applicable when the approach was linked with STAR procedures other than the ARBEY STAR.

¹ A STAR is a published instrument flight rules arrival route that links the en route airways system to a fix at or near the destination airport.

² An NDB is a radio transmitter at a known location, used as a navigational aid. The signal transmitted does not include inherent directional information.

³ The minimum en route altitude (MEA) and the minimum terrain clearance altitude (MTCA) are calculated differently, and both are depicted on the STAR chart used by the operator. Only the minimum en route altitude is depicted on the corresponding Airservices Australia STAR chart.

Figure 2: Excerpt from the RNAV-U (RNP) runway 16 approach chart used by the operator depicting two altitudes at BOL



Source: Aircraft operator – image cropped by the ATSB

As the aircraft approached BUNKY, air traffic control (ATC) cleared the crew to descend to 4,000 ft, and to conduct the RNAV-U (RNP) runway 16 approach. ATC radar data shows that the aircraft overflew BUNKY at 5,000 ft, then continued descent, passing through 4,000 ft about 5 NM prior to BOL. During the approach setup, the Flight Management Computer (FMC)⁴ indicated an altitude constraint for BOL of ‘at or above 3,000 ft’. The crew then selected this to an ‘at 3,000 ft’ constraint, which programmed the aircraft to overfly BOL at a ‘hard altitude’ of 3,000 ft.

Descent then continued, and ATC received a Minimum Safe Altitude Warning (MSAW)⁵ alert, as the aircraft descended through 3,400 ft about 4 NM prior to BOL (Figure 3). ATC questioned the crew about their altitude, and advised them that the relevant radar lowest safe altitude was 3,200 ft. Moments later, the aircraft passed over BOL at about 3,000 ft and maintained that altitude until intercepting the vertical profile of the RNAV-U (RNP) runway 16 approach. ATC then transferred the crew to the next frequency, and the crew confirmed they had the correct QNH setting.⁶ The approach continued for an uneventful landing.


A subsequent review of the ATC radar data showed that the aircraft left controlled airspace as it descended through 3,500 ft. The aircraft was briefly outside controlled airspace until it reached the 15 NM airspace boundary step, where the lower limit of controlled airspace became 2,500 ft. There was no report of conflict with other traffic outside of controlled airspace. Throughout the incident, the crew maintained visual contact with the terrain, and could see the airport environment from some distance out. No aircraft ground proximity warning system alerts were triggered during the incident.

⁴ The FMC provides aircraft navigation, lateral and vertical guidance, and aircraft performance functions.

⁵ MSAW is a ground-based system intended to alert ATC to an increased risk of an aircraft collision with terrain.

⁶ QNH is an altimeter barometric pressure subscale setting. With QNH set, an altimeter provides an indication of the height of the aircraft above mean sea level.

Figure 3: ATC radar image at the time the MSAW alert activated



Source: Airservices Australia (modified by the ATSB)

Review of the factors identified in the investigation

The operator's investigation found that descent below the 4,000 ft altitude restriction at BOL occurred because the crew selected the 'hard altitude' of 3,000 ft for BOL. The potential for deviation below the 4,000 ft minimum altitude restriction at BOL was increased by factors related to aeronautical charts and the FMC navigation database. Some of these factors are discussed in the following paragraphs.

The ATSB obtained comments and responses from involved parties including:

- the United Arab Emirates General Civil Aviation Authority on behalf of Emirates Airlines
- Airservices Australia
- the Civil Aviation Safety Authority (CASA).

The RNP approach had been designed by GE Naverus (Naverus), based on information in the Airservices Australia Aeronautical Information Package (AIP). The charts and FMC data used by Emirates were supplied by LIDO. LIDO developed the charts and database based on information in the Airservices AIP.

Procedure design – level depiction on the ARBEY STAR

No minimum altitude was specified at BOL on the ARBEY FOUR STAR.

Operator comments

Within the STAR, BOL had a coded speed restriction of a maximum 185 kt for approaches to runway 16, but did not specify a minimum crossing altitude. This allowed arrivals from other directions to cross BOL at a minimum altitude of 3,000 ft, instead of 4,000 ft as required via ARBEY. This conditional altitude restriction was specified in the approach charts only and not on the STAR chart. This procedure design did not protect the MEA of 3,400 ft on the arrival segment from position BUNKY to position BOL by a 'hard procedural altitude'. BOL is located at a distance of 11.6 NM from runway 16 and a crossing altitude of 4,000 ft would permit a constant approach angle crossing BOL on a 3.0° vertical descent path. Based on this, a lower crossing altitude (3,000 ft) for other arrival directions does not seem necessary.

The operator suggested that Airservices Australia consider procedural amendments to specify a minimum crossing altitude over BOL (of 4,000 ft or above) for all approaches and within the STAR design. This would protect against descents below MEA (and outside controlled airspace) within the arrival segment from BUNKY to BOL. It would also satisfy the requirement of Airservices Australia to be able to specify higher crossing altitudes (above 4,000 ft) for traffic separation. If Airservices Australia, as the State AIP, changed the procedure design, the various chart providers would then amend their corresponding FMC/FMS databases as well as the STAR and instrument approach charts.

CASA comments

CASA suggested a possible solution would be to include the altitude restriction in the STAR chart. This would then make the altitude obvious on the text and plan view, and the altitude restriction would be coded in the FMS. They also found that the overall complexity of the STAR chart did not aid pilots' awareness.

Airservices response

In controlled airspace, the approach procedures are designed to keep aircraft 500 ft above the control area steps. The 4,000 ft minimum altitude was designed to keep aircraft in controlled airspace prior to BOL, rather than for terrain clearance.

Airservices further commented that a minimum altitude of 4,000 ft was not depicted on the STAR chart at BOL, as BOL was also applicable to the runway 27 arrival. This allows ATC to assign a higher altitude at that point for a runway 27 arrival due to potential runway 34 departures. No altitudes are depicted because two (or more) levels would be required to cater for the different

runways. Only one level is permitted to be depicted against a waypoint (for a STAR) to avoid potential confusion as per Section 1-1-22 of Airservices 'Departure, Arrival and Air Route Management Design Rules' manual (ATS-MAN-0010).

Altitude requirements are not always specified on a STAR chart, and ATC is generally responsible for deciding whether altitudes are to be included or not. This occurs in the procedure design phase. When they are not included on the chart, ATC assigns individual altitudes to aircraft in order to facilitate vertical separation between them and assure terrain clearance.

RNAV-(U) RNP runway 16 approach chart design

Approaches with multiple altitudes at a common fix


Airservices withdrew the RNAV-U (RNP) runway 16 approach early in 2015. Its withdrawal was not related to this incident. The ATSB reviewed all Australian approach charts published in the AIP Departure and Approach Procedures (DAP) current at the time of writing. The approach charts with a discrepancy between the STAR minimum segment altitude and the approach start altitude were Melbourne approach charts ILS – X, Y and Z runway 16, RNAV Z (GNSS) runways 16 and 27. No other Australian approach charts existed with that condition.

Chart depiction of the altitude restriction at BOL – operator comments

The operator reported that the absence of altitude restriction information on the STAR chart reduced the level of protection against deviation below the BOL minimum altitude restriction. The 4,000 ft altitude restriction at BOL when tracking from ARBEY STAR was physically depicted below the 3,000 ft altitude restriction applicable to other STAR procedures (see Figure 4a). This may also have influenced the crew’s interpretation of the FMC altitude.


The following two figures show a comparison of two presentation options for multiple arrival altitudes. These altitudes are boxed in red.

Figure 4a: RNAV (RNP) approach chart used by the crew



Source: GCAA for chart provider (LIDO) modified by the ATSB

Figure 4b: RNAV (GNSS) Z approach chart



Source: GCAA for chart provider (LIDO) modified by the ATSB

Chart provider comments

The chart provider (LIDO) commented that presentation of information on a chart is normally at the discretion of the chart editor and based on:

- the amount of information which needs to be charted
- the amount of information already on the chart
- the space available for the information, based on standard font sizes.

If the information can be charted clearly using a leader line, this is used (see Figure 4a). As soon as the information exceeds two lines, the preference is usually for the information framed together in a box with a ball note⁷ at the point in question (see Figure 4b).


The chart provider advised that on the RNAV (RNP) chart the higher value (4000) should have been depicted above the lower value (3000). They reiterated that the approach chart (Figure 4a) used in this incident is no longer valid.

RNAV-U (RNP) runway 16 approach chart profile view

The approach chart provided a vertical profile view of the approach, but the view began immediately prior to intermediate fix (IF), waypoint UGARU, which is 4.4 NM beyond BOL (Figure 5a). As such, there was no profile view information on the approach chart for the approach from the initial approach fix (IAF) BOL, to UGARU. Had this information been present in a vertical profile, it may have alerted the crew to the different altitude requirements at BOL, associated with the different STAR procedures.

⁷ The ball note, as depicted in Figure 3b, includes the black circle with reference number 1 at BOL, with the explanation in the box using the same black dot (or 'ball') and matching reference number (or letter).

Figure 5a: Excerpt from the RNAV-U (RNP) runway 16 approach chart used by the operator showing vertical profile information




Source: Aircraft operator

Vertical profile view – operator comments

The operator noted that the profile view of Naverus charts was inconsistent with similar Airservices Australia charts. For example, the RNAV-Z (GNSS) runway 16 approach chart, which was designed by Airservices Australia, provided the important hazard information of the different minimum crossing altitudes over BOL in the profile view (Figure 5b). However the RNAV-U (RNP) runway 16 approach chart, which was designed by Naverus, depicted these altitudes in the plan view only. The operator considered that extension of the profile view, as published on similar Airservices Australia charts, would assist flight crews to select the correct altitude for the IAF.

Figure 5b: Excerpt from the Airservices RNAV-Z (GNSS) runway 16 approach chart for comparison



Source: Airservices Australia

The operator suggested that the profile view of the Naverus charts should be amended to conform to that of the Airservices Australia charts.

Airservices response

Airservices advised that the standard for the approach profile view was to commence at the final approach fix (FAF), and not to include the initial approach fix (IAF). Airservices opted to trial the inclusion of the IAF, in this case BOL, in the profile view of other similar charts. While its inclusion made the approach altitude clearer, Airservices stated that it was not likely to be adopted as the convention, either generally by Airservices or internationally. Naverus charts conform to the ICAO standard, and therefore the profile view did not commence at the IAF.

FMC navigation data

Consistent with the STAR chart, the ARBEY 4U STAR FMC navigation data did not include an altitude restriction at BOL (Figure 6). FMC navigation data for the RNAV-U (RNP) runway 16 approach included an altitude restriction at BOL, but that altitude restriction was ‘3000A’ (meaning ‘at or above’ 3,000 ft) (Figure 7). The 3,000 ft restriction was applicable to a number of STARs that linked with the RNAV-U (RNP) runway 16 approach. But it was not applicable to the ARBEY STAR which had a 4,000 ft restriction.

Figure 6: ARBEY 4U STAR FMC navigation data

Apt	Ident	Via	Rwy	TrAlt	Fix	Type	Fix Latitude	Fix Longitude	T	PT	O	M	Cs/Hd	Alt1	CAS	RNP	
YMML	ARBE4U	STARCR	16	11000	ARBEY	WPT	NOT FOR NAVIGATION										
YMML	ARBE4U	STARCR	16	11000	BUNKY	WPT								9000B	230	1	
YMML	ARBE4U	STARCR	16	11000	BOL	NDB	S37-27-43.92	E144-47-53.58		TF					185	1	

Source: Aircraft operator modified by the ATSB

Figure 7: RNAV-U (RNP) runway 16 approach FMC navigation data

Apt	Ident	Via	Rwy	TrAlt	Fix	Type	Fix Latitude	Fix Longitude	T	PT	O	M	Alt1	FPA	CAS	RNP
YMML	RNV16-U	APP	16	11000	BOL	NDB	S37-27-43.92	E144-47-53.58		IF			3000A			
YMML	RNV16-U	APP	16	11000	UPKAN	WPT	S37-30-03.42	E144-48-23.63		TF			3000A			0.3
YMML	RNV16-U	APP	16	11000	UGARU	WPT							2800A			0.3
YMML	RNV16-U	APP	16	11000	ML658	WPT							2000A			0.3
YMML	RNV16-U	APP	16	11000	ML649	WPT	S37-35-28.10	E144-49-24.04		TF			1700			0.3
YMML	RNV16-U	APP	16	11000	RW16	RWY	S37-39-11.50	E144-50-05.67		TF	Y		480	-2.99		0.3

Source: Aircraft operator modified by the ATSB

Compliance with the published procedure on this occasion required the crew to modify the FMC vertical profile at BOL by increasing the ‘at or above’ altitude restriction from 3,000 ft to 4,000 ft. Any requirement to modify the vertical profile brings about the potential to introduce errors, the consequences of which may be more significant when the FMC default altitude needs to be increased. If an error is introduced when the FMC vertical profile is modified, vertical path indications displayed to the crew during the approach may be misleading.

FCOM procedure

At the time of the incident, the FCOM stated that crews could change an FMC IAF ‘at or above’ altitude constraint, to an ‘at’ altitude constraint, using the **same** altitude. Technically therefore, the crew were unable to change the coded 3000A to the correct 4000A. This ambiguity within the FCOM procedure was raised with the aircraft manufacturer via the fleet technical pilots. At the time of publication, a response from the manufacturer was still pending.

FMC approach altitude

As depicted in Figure 6, there was no altitude on the STAR coded in the FMC, so when the crew selected approach mode, the 3000A appeared as the relevant altitude restriction for BOL. Only one altitude can be selected by the FMC. The ATSB was unable to clarify what coding logic was applied to determine which altitude is selected when two are provided.

The aircraft operator commented that they did not raise this issue with the FMC database provider, as the database coding reflects the AIP procedure design. The aircraft operator considered the conditional altitude over the waypoint BOL to be a procedure design weakness and raised that with Airservices Australia accordingly. The approach is no longer valid, but the operator intends to closely monitor for this issue in any new approaches.

Safety action

Whether or not the ATSB identifies safety issues in the course of an investigation, relevant organisations may proactively initiate safety action in order to reduce their safety risk. The ATSB has been advised of the following proactive safety action in response to this occurrence.

Aircraft operator

Crew awareness of restrictions on STAR

Soon after the occurrence, the aircraft operator published a company Notice to Airmen (NOTAM) for crew awareness. The NOTAM pointed out that approaches into Melbourne may include altitude restrictions that depend on the particular STAR being flown. The NOTAM also pointed out that some altitude restrictions may be depicted on the approach chart plan view only, and not necessarily on the relevant STAR chart, or the approach chart profile view. The NOTAM advised crews to exercise caution when reviewing STAR and approach procedures to ensure that all applicable altitude restrictions were observed.

Flight crew operations manual

The operator intends to reconsider Flight Crew Operations Manual guidance dealing with the benefits of changing initial approach fix 'at or above' altitude restrictions to hard altitudes, and discuss the depiction of altitude restrictions on the relevant charts with the chart provider.

Flight management computer coding

The operator has identified the FMC coding issue as a threat in their Hazard Identification and Risk Assessment statements. All new destinations and also, within the review cycle, existing destinations, will be checked against this threat and corrective action will be taken if applicable.

Airservices and CASA

CASA and Airservices intend to discuss the coding of the FMC at the next international instrument procedures panel, where an 'integration' subgroup includes FMC coding specialists. The aim of the discussion is to ensure the charts are used in the cockpit the way they are intended.

Safety message

For operators, this incident highlights the need for careful attention to FMC navigation data management, particularly any procedures that relate to crew modification of navigation data. Operators should remain mindful that any manipulation of FMC navigation data by flight crew has the potential to introduce errors. Additionally, operators are encouraged to work closely with aeronautical information service providers to ensure that aeronautical charts (and any other operational information) are presented in a manner that minimises ambiguity and reduces the potential for misinterpretation.

For flight crew, this incident highlights the need for careful attention to approach procedure documentation and FMC navigation data management.

For producers and providers of aeronautical information products, a guiding principle specified in *Procedures for Air Navigation Services, Aircraft Operations* is to keep all charts as simple as possible. This may assist in reducing flight crew workload and the risk of error, and coding issues when entering data into flight management systems.

General details

Occurrence details

Date and time:	18 July 2014 – 0710 EST	
Occurrence category:	Incident	
Primary occurrence type:	Flight below minimum altitude	
Location:	Near Melbourne, Victoria	
	Latitude: 37° 23.000' S	Longitude: 144° 47.000' E

Aircraft details

Manufacturer and model:	Boeing 777-36NER	
Registration:	A6-ECO	
Operator:	Emirates Airlines	
Serial number:	37706/765	
Type of operation:	Air Transport High Capacity	
Persons on board:	Crew – Unknown	Passengers – Unknown
Injuries:	Crew – Nil	Passengers – Nil
Damage:	None	

About the ATSB

The Australian Transport Safety Bureau (ATSB) is an independent Commonwealth Government statutory agency. The ATSB is governed by a Commission and is entirely separate from transport regulators, policy makers and service providers. The ATSB's function is to improve safety and public confidence in the aviation, marine and rail modes of transport through excellence in: independent investigation of transport accidents and other safety occurrences; safety data recording, analysis and research; and fostering safety awareness, knowledge and action.

The ATSB is responsible for investigating accidents and other transport safety matters involving civil aviation, marine and rail operations in Australia that fall within Commonwealth jurisdiction, as well as participating in overseas investigations involving Australian registered aircraft and ships. A primary concern is the safety of commercial transport, with particular regard to the travelling public.

The ATSB performs its functions in accordance with the provisions of the *Transport Safety Investigation Act 2003* and Regulations and, where applicable, relevant international agreements.

The object of a safety investigation is to identify and reduce safety-related risk. ATSB investigations determine and communicate the safety factors related to the transport safety matter being investigated.

It is not a function of the ATSB to apportion blame or determine liability. At the same time, an investigation report must include factual material of sufficient weight to support the analysis and findings. At all times the ATSB endeavours to balance the use of material that could imply adverse comment with the need to properly explain what happened, and why, in a fair and unbiased manner.

About this report

Decisions regarding whether to conduct an investigation, and the scope of an investigation, are based on many factors, including the level of safety benefit likely to be obtained from an investigation. For this occurrence, a limited-scope, fact-gathering investigation was conducted in

order to produce a short summary report, and allow for greater industry awareness of potential safety issues and possible safety actions.