



**Australian Government**

**Australian Transport Safety Bureau**

**ATSB TRANSPORT SAFETY INVESTIGATION REPORT**

Aviation Safety Incident Report – 200403110

Final

**Engine failure - Melbourne Airport, Victoria  
25-Aug-2004  
Boeing Company 777-312  
9V-SYB**





**Australian Government**  

---

**Australian Transport Safety Bureau**

**ATSB TRANSPORT SAFETY INVESTIGATION REPORT**

Aviation Occurrence Report

200403110

Final

**Engine failure - Melbourne Airport**

**25 Aug 2004**

**Boeing Company 777-312, 9V-SYB**

---

Released in accordance with section 25 of the *Transport Safety Investigation Act 2003*

*Published by:* Australian Transport Safety Bureau  
*Postal address:* PO Box 967, Civic Square ACT 2608  
*Office location:* 15 Mort Street, Canberra City, Australian Capital Territory  
*Telephone:* 1800 621 372; from overseas + 61 2 6274 6590  
Accident and serious incident notification: 1800 011 034 (24 hours)  
*Facsimile:* 02 6274 6474; from overseas + 61 2 6274 6474  
*E-mail:* [atsbinfo@atsb.gov.au](mailto:atsbinfo@atsb.gov.au)  
*Internet:* [www.atsb.gov.au](http://www.atsb.gov.au)

© Commonwealth of Australia 2006.

This work is copyright. In the interests of enhancing the value of the information contained in this publication you may copy, download, display, print, reproduce and distribute this material in unaltered form (retaining this notice). However, copyright in the material obtained from non-Commonwealth agencies, private individuals or organisations, belongs to those agencies, individuals or organisations. Where you want to use their material you will need to contact them directly.

Subject to the provisions of the *Copyright Act 1968*, you must not make any other use of the material in this publication unless you have the permission of the Australian Transport Safety Bureau.

Please direct requests for further information or authorisation to:

Commonwealth Copyright Administration, Copyright Law Branch  
Attorney-General's Department, Robert Garran Offices, National Circuit, Barton ACT 2600  
[www.ag.gov.au/cca](http://www.ag.gov.au/cca)

ISBN and formal report title: see 'Document retrieval information' on page iv.

---

# CONTENTS

---

|  |              |
|--|--------------|
| <b>THE AUSTRALIAN TRANSPORT SAFETY BUREAU .....</b>                          | <b>v</b>     |
| <b>EXECUTIVE SUMMARY .....</b>   | <b>vi</b>    |
| <b>FACTUAL INFORMATION.....</b>  | <b>1</b>     |
| History of the flight .....  | 1            |
| Damage to aircraft .....   | 2            |
| Aircraft Information.....  | 3            |
| Left Engine Information.....   | 3            |
| Recorded Flight Information.....   | 3            |
| Left engine examination.....   | 4            |
| Casing liner examination.....  | 5            |
| Engine health monitoring .....   | 5            |
| Failed composite panel examination .....                                     | 6            |
| <b>ANALYSIS.....</b>   | <b>7</b>     |
| <b>FINDINGS .....</b>  | <b>8</b>     |
| Contributing factors .....   | 8            |
| Other safety factors.....  | 8            |
| <b>SAFETY ACTION.....</b>  | <b>9</b>     |
| Engine manufacturer.....   | 9            |
| <b>Appendix A – Rolls-Royce Service component investigation report .....</b> | <b>11</b>    |
| <b>Appendix B - Praxair Investigation Report.....</b>                        | <b>.....</b> |
| <b>Addendum to Appendix B.....</b>   | <b>.....</b> |
| <b>Appendix C - ATSB Technical Analysis Report.....</b>                      | <b>.....</b> |

---

## DOCUMENT RETRIEVAL INFORMATION

---

| Report No. | Publication date | No. of pages | ISBN          |
|------------|------------------|--------------|---------------|
| 20043110   | October 2006     | 149          | 1 921164 11 5 |

---

### Publication title

Engine Failure – Melbourne Airport, 25 August 2004, Boeing Company 777-312, 9V-SYB

---

### Prepared by

Australian Transport Safety Bureau  
PO Box 967, Civic Square ACT 2608 Australia  
[www.atsb.gov.au](http://www.atsb.gov.au)

---

### Acknowledgements

Singapore AAIB, UK AAIB, Singapore Airlines, SAESL, Rolls-Royce UK, Praxair

---

### Abstract

At approximately 0104 Eastern Standard Time on 25 Aug 2004, the left engine surged during takeoff from Runway 34 at Melbourne Airport. The crew of the Singaporean registered Boeing 777-312 aircraft, 9V-SYB, subsequently reported that the surge occurred just at  $V_1$ . The crew elected to continue the takeoff and the left engine surged multiple times during the departure, until they shutdown the engine. Due to forecast turbulence, the crew maintained an altitude of approximately 3,000 ft above ground level to dump fuel and reduce the aircraft's weight for landing. Air Traffic Services vectored the aircraft over Port Phillip Bay for the fuel dump, which took approximately 1 hour, before the aircraft was returned to Melbourne for an uneventful single-engine landing. There were 300 persons on board and there were no reported injuries.

An examination of the engine found that several of the High Pressure Compressor (HPC) casing liners had eroded to the point of reducing the efficiency of the HPC.

---

---

# THE AUSTRALIAN TRANSPORT SAFETY BUREAU

---

The Australian Transport Safety Bureau (ATSB) is an operationally independent multi-modal Bureau within the Australian Government Department of Transport and Regional Services. ATSB investigations are independent of regulatory, operator or other external bodies.

The ATSB is responsible for investigating accidents and other transport safety matters involving civil aviation, marine and rail operations in Australia that fall within Commonwealth jurisdiction, as well as participating in overseas investigations involving Australian registered aircraft and ships. A primary concern is the safety of commercial transport, with particular regard to fare-paying passenger operations. Accordingly, the ATSB also conducts investigations and studies of the transport system to identify underlying factors and trends that have the potential to adversely affect safety.

The ATSB performs its functions in accordance with the provisions of the *Transport Safety Investigation Act 2003* and, where applicable, relevant international agreements. The object of a safety investigation is to determine the circumstances in order to prevent other similar events. The results of these determinations form the basis for safety action, including recommendations where necessary. As with equivalent overseas organisations, the ATSB has no power to implement its recommendations.

It is not the object of an investigation to determine blame or liability. However, it should be recognised that an investigation report must include factual material of sufficient weight to support the analysis and findings. That material will at times contain information reflecting on the performance of individuals and organisations, and how their actions may have contributed to the outcomes of the matter under investigation. At all times the ATSB endeavours to balance the use of material that could imply adverse comment with the need to properly explain what happened, and why, in a fair and unbiased manner.

Central to the ATSB's investigation of transport safety matters is the early identification of safety issues in the transport environment. While the Bureau issues recommendations to regulatory authorities, industry, or other agencies in order to address safety issues, its preference is for organisations to make safety enhancements during the course of an investigation. The Bureau prefers to report positive safety action in its final reports rather than making formal recommendations. Recommendations may be issued in conjunction with ATSB reports or independently. A safety issue may lead to a number of similar recommendations, each issued to a different agency.

The ATSB does not have the resources to carry out a full cost-benefit analysis of each safety recommendation. The cost of a recommendation must be balanced against its benefits to safety, and transport safety involves the whole community. Such analysis is a matter for the body to which the recommendation is addressed (for example, the relevant regulatory authority in aviation, marine or rail in consultation with the industry).

---

## EXECUTIVE SUMMARY

---

At approximately 0104 Eastern Standard Time on 25 Aug 2004, the left engine surged during takeoff from Runway 34 at Melbourne Airport. The crew of the Singaporean registered Boeing 777-312 aircraft, 9V-SYB, subsequently reported that the surge occurred just at  $V_1$ <sup>1</sup>. The crew elected to continue the takeoff and the left engine surged multiple times during the departure, until they shutdown the engine. Due to forecast turbulence, the crew maintained an altitude of approximately 3,000 ft above ground level to dump fuel and reduce the aircraft's weight for landing. Air Traffic Services vectored the aircraft over Port Phillip Bay for the fuel dump, which took approximately 1 hour, before the aircraft was returned to Melbourne for an uneventful single-engine landing. There were 300 persons on board and there were no reported injuries.

An examination of the engine found that several of the High Pressure Compressor (HPC) casing liners had eroded to the point of reducing the efficiency of the HPC.

As a result of the occurrence, the engine manufacturer has taken a number of steps to identify this failure mode during engine trend monitoring in order to reduce the likelihood of a recurrence.

---

<sup>1</sup>  $V_1$  is the take-off decision point at which, should the critical engine fail, the pilot can elect to abandon the takeoff.

---

## FACTUAL INFORMATION

---

### History of the flight

At approximately 0104 Eastern Standard Time, on 25 Aug 2004, the left engine surged during takeoff from Runway 34 at Melbourne Airport. The crew of the Singaporean registered Boeing 777-312 aircraft, 9V-SYB, subsequently reported that the surge occurred just at  $V_{1^2}$ . The crew elected to continue the takeoff and the left engine surged multiple times during the departure, until they shutdown the engine. Melbourne Airport officers reported an amount of debris on Runway 34.

Due to forecast turbulence, the crew maintained an altitude of approximately 3,000 ft above ground level to dump fuel and reduce the aircraft weight for landing. Air Traffic Services vectored the aircraft over Port Phillip Bay for the fuel dump, which took approximately 1 hour before the aircraft was returned to Melbourne for an uneventful single-engine landing. There were 300 persons on board and there were no reported injuries.

The Australian Transport Safety Bureau (ATSB) dispatched an investigation team to Melbourne to examine the aircraft, where no obvious external damage was evident (Figure 1). The ATSB examination revealed that one of the left engine's composite core panels had broken and separated from the engine during the engine surge (Figure 2). The left engine, a Rolls-Royce Trent 800, Serial number 51067, exhibited only minor damage to a number of components. A borescope inspection of the engine compressor section revealed no significant anomalies with the engine compressor or turbine rotors or stators.


**Figure 1: Trent 800 engine S/No. 51067 fitted to the left position of 9V-SYB**



---

<sup>2</sup>  $V_1$  is the take-off decision point at which, should the critical engine fail, the pilot can elect to abandon the takeoff.


**Figure 2: Separated composite engine core panel in cold stream duct**



### **Damage to aircraft**

An amount of debris was liberated from the separated left engine core composite panel and was recovered from the departure runway (Figure 3).

**Figure 3: Composite panel remnants recovered from runway**



## Aircraft Information

|                     |                |
|---------------------|----------------|
| Manufacturer        | Boeing Company |
| Model               | 777-312        |
| Serial number       | 28516          |
| Registration        | 9V-SYB         |
| Year of manufacture | 1998           |

## Left Engine Information

|                          |                      |
|--------------------------|----------------------|
| Manufacturer             | Rolls-Royce Pty Ltd. |
| Model                    | Trent 800            |
| Serial number            | 51067                |
| Total time in service    | 15,614 Hrs           |
| Cycles in service        | 4,527                |
| Time since last repair   | 2,256 Hrs            |
| Cycles since last repair | 614                  |
| Date of last rework      | Feb 2004             |
| Date fitted to 9V-SYB    | Feb 2004             |

## Recorded Flight Information

The aircraft was fitted with both a solid state flight data recorder (FDR) and cockpit voice recorder (CVR). It was also equipped with an optical Quick Access Recorder (QAR). All recording devices were removed from the aircraft and forwarded to the ATSB to download the recorded information. The downloaded information was of good quality and indicated the following:

- During the takeoff roll, a loud bang was recorded on the CVR. This bang occurred 0.8 seconds before the automatic  $V_1$  annunciation. Over the next 70 seconds, before the engine was shutdown, 57 bangs were audible on the CVR recording.
- At the time of the initial engine surge, the left engine  $N_1$  values<sup>3</sup> decreased while the  $N_2$  and  $N_3$  values showed uncommanded increases.
- The maximum turbine gas temperature recorded for the left engine during the event was 910 degrees C.

A plot of the significant recorded left engine data is reproduced as Figure 15 on page 34 of Appendix A.

---


<sup>3</sup>  $N$  values refer to the compressor rotating speeds.  $N_1$  represents the Low Pressure compressor,  $N_2$  represents the Intermediate Pressure compressor and  $N_3$  the High Pressure compressor.

## Left engine examination


The left engine was shipped to a joint engine overhaul facility in Singapore for detailed examination, supervised by investigators from the ATSB and the Air Accident Investigation Bureau of Singapore.

The engine examination revealed that the high pressure compressor (HPC) casing abrasion linings had deteriorated in service. There was a visible loss of abrasion rotor lining on several of the HPC compressor casings (Figures 4 and 5). The engine manufacturer advised that the HPC stage-6 casing-to-rotor clearance was critical to engine airflow control at the take-off thrust setting.

**Figure 4: HPC stage 6 casing and liner assembly**



**Figure 5: Detail of HPC stage 6 casing abrasion liner erosion**



### **Casing liner examination**

All six HPC stage casings were sent to the engine manufacturer, Rolls-Royce in Derby, United Kingdom (UK), for examination, under the supervision of an investigator from the UK Air Accidents Investigation Branch. A copy of the detailed liner examination by Rolls-Royce is contained in Appendix A. The contractor responsible for the application of the lining material to a number of the casing liners, Praxair Surface Technologies, submitted a separate report to the ATSB based on their own examinations. A copy of that report is contained in Appendix B.

### **Engine health monitoring**

Prior to this incident on 25 Aug 2004, the engine manufacturer had been monitoring the in-service health of Trent-800 engines. On 4 August 2004, an Engine Health Monitoring (EHM) alert was issued to the aircraft operator due to the identification of a step change in the engine's Turbine Gas Temperature (TGT) margin. As a result of this alert, the aircraft operator conducted the required engine inspection, including a borescope inspection of the HPC. Only minor damage, within acceptable limits, was noted to a small number of the stage-6 HPC blades, and the engine was returned to service. The borescope inspection only permitted limited examination of the HPC casing liner material in the immediate vicinity of the borescope inspection port.

Following this incident, the engine manufacturer conducted a review of other potentially affected engines with deteriorating HPC efficiency. That review found that two other Trent-800 engines exhibited performance degradation due to erosion of their HPC linings and both engines were removed from service.

## Failed composite panel examination

An examination of the separated engine core composite panel indicated that all the panel fasteners were retained in their mounts after the panel failed (Figure 6). One fastener hole showed signs of wear, but there was no direct evidence to suggest that the fitting was loose at the time of the failure (Figure 7). It was apparent from wear in the fastener fitting that it may have been loose previously, and that this looseness may have contributed to some prior weakening of the panel structure, which contributed to the panel failure during the engine surge event.

**Figure 6: Typical composite panel failure around mounting point**



**Figure 7: Elongated fastener hole showing signs of wear**



---

## ANALYSIS

---

The left engine surged at  $V_1$  during takeoff from Melbourne Airport. The actions by the crew to continue the takeoff were appropriate for the circumstances and ensured a successful, single-engine, return to the airport.

The engine surge was as a direct result of a breakdown of the airflow within in the engine High Pressure Compressor (HPC). Directly contributing to that condition was a reduction in the HPC efficiency associated with the erosion and loss of HPC casing lining material, particularly at the rear stages of the HPC. The stage-6 lining material loss resulted in increased rotor tip clearances. The stage-6 lining material loss was the most critical stage for airflow control through the HPC during the takeoff.

The loss of HPC casing lining material was discussed in both the engine manufacturer and the sprayed coating contractors' reports (Appendixes A and B). As a result of the differing views presented in each report, the Australian Transport Safety Bureau (ATSB) conducted a review of both reports to determine the likely factors associated with lining material loss from the HPC casings. That review is included as Appendix C.

The ATSB review concluded that the coating quality issues were the most probable factor contributing to the premature degradation of the HPC casing lining leading to the engine surge. While acknowledging the possibility that oxidation may have weakened the coating particle cohesive strength, the significance of this effect had not been quantified in respect of the performance of the lining in service. Other proposed contributors such as Calcia-Magnesia-Alumina-Silica (CMAS) ingestion, extended operation at elevated temperatures and the effects of thermal cycling were not substantiated by evidence. Similar casing liner issues were also apparent in all the other HPC casing liner stages in the engine.

If a step change was noted in the engine Turbine Gas Temperature (TGT) margin, the Engine Health Monitoring (EHM) program of the Trent-800 engines required a visual inspection of the HPC. However, this inspection was limited to examining the condition of the HPC compressor blades and was not capable of determining the extent of any deterioration of the HPC casing lining material.

The failed engine core composite panel was secondary to the engine surge event and did not contribute to the engine failure.

---

## **FINDINGS**

---

### **Contributing factors**

- The left engine surged during takeoff.
- The left engine High Pressure Compressor (HPC) casing liners exhibited lining material loss.
- The left engine HPC stage-6 casing lining material was eroded, increasing the rotor tip clearance and reducing the efficiency of the stage at take-off thrust.

### **Other safety factors**

- The Engine Health Monitoring procedures detected the deterioration of the efficiency of the HPC, however the subsequent inspection requirements were unable to detect any deterioration of HPC lining material.

---

## **SAFETY ACTION**

---

### **Engine manufacturer**

As a result of this occurrence, the engine manufacturer, Rolls-Royce UK, advised the Australian Transport Safety Bureau that they have taken the following actions:

Two engines that were identified as being at risk of surging due to degraded High Pressure Compressor (HPC) efficiency were removed from service.

The Engine Health Monitoring (EHM) procedures have been changed. If an EHM alert is issued and troubleshooting reveals no findings to explain the observed change, the engine manufacturer will review engine parameter data in more detail. This may lead to a recommendation that the engine is removed from service.

The aircraft maintenance manual will be updated to include an inspection check of the condition of the rotor path lining immediately adjacent to the borescope port hole and to contact the engine manufacturer if no evidence of lining loss.

The engine manufacturer has also developed an algorithm to alert changes of HPC efficiency as part of the suite of automatically generated alerts produced for engine health monitoring purposes.

