

**Aviation Safety Investigation Report  
198703487**

**Mitsubishi MU-2B-25K**

**14 July 1987**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 198703487

**Occurrence Type:** Accident

**Location:** Toowoomba QLD

**Date:** 14 July 1987

**Time:** N/K

**Highest Injury Level:** Nil

**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	6
<b>Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>7</b>

**Aircraft Details:** Mitsubishi MU-2B-25K

**Registration:** VH-MUK

**Serial Number:** 310

**Operation Type:** Charter (Passenger)

**Damage Level:** Substantial

**Departure Point:** Moomba SA

**Departure Time:** N/K

**Destination:** Toowoomba QLD

**Approved for Release:** September 28th 1987

**Circumstances:**

The pilot stated that the wind was blowing directly across the strip and he joined the circuit for a landing on runway 29. He reported that when the aircraft was on final approach it encountered a significant tailwind, and a missed approach was carried out, followed by a "tear-drop" style turn to align the aircraft on final for runway 11. The pilot stated that after touching down on the mainwheels, the nosewheel was lowered and he heard a bang before the nose of the aircraft contacted the runway. The aircraft slid along the runway before coming to rest just off the sealed surface. An inspection of the landing gear assembly revealed that the nosegear downlock linkage failed due to overload forces causing the nosegear to retract. The landing gear mechanism was also bent by overload forces. No evidence could be found to indicate that defects in the landing gear system existed prior to this landing. The nature of the failure of the nosegear is consistent with heavy nosewheel runway contact.