

**Aviation Safety Investigation Report
199700093**

**Alexander Schleicher GmbH & Co
ASW 17**

13 January 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

After being released he turned left, flew for a few hundred metres before turning right, and then outlanded into a small field covered in stubble. Once on the ground the glider ground looped in the stubble and slid backwards into a fence. The glider was substantially damaged.

After the accident the glider was found to be configured with the flaps in the "negative flap" setting. This setting is a feature that is used to reduce drag during high speed cruise. The negative flap setting can also be used in the first segment of a takeoff roll to increase the low speed effectiveness of the ailerons. When this procedure is employed the flaps are reconfigured to the takeoff setting as soon as the wings are levelled and under positive aileron control. The continued use of the negative flap setting during takeoff and climb seriously degrades the climb performance of the glider.

The pilot was not able to explain to the investigator from the Gliding Federation of Australia(GFA) why the flaps were still selected to an inappropriate setting.

There is no evidence of the flaps having moved as a function of the accident sequence therefore it can be concluded that the pilot did not apply landing flap during the approach into the stubble field. It is probable that the flap setting was not changed during the takeoff run. This would explain the lack of climb performance experienced during the takeoff sequence.

