

Australian Government Australian Transport Safety Bureau

Failure to pressurise, Beech Aircraft Corp B200T

34 km west south-west of Northam, WA, on 27 September 2022

ATSB Transport Safety Report

Aviation Occurrence Brief AB-2022-014 Final – 16 December 2020

AB-2022-014

Occurrence Briefs are concise reports that detail the facts surrounding a transport safety occurrence, as received in the initial notification and any follow-up enquiries. They provide an opportunity to share safety messages in the absence of an investigation.

What happened

On 27 September 2022 at 0845 local time, the pilot of a Beech Aircraft Corp B200T was conducting a ferry flight from Jandakot to Kalgoorlie-Boulder, Western Australia. Prior to departure, the pilot conducted engine run-up and cabin pressurisation checks confirming serviceability. During the initial climb, the pilot conducted the after take-off checks, including to ensure the bleed air valves¹ were open and the cabin was pressurising. This was confirmed by a positive rate of climb indication on the pressurisation vertical speed indicator. Normal operation of the pressurisation system was confirmed again passing 10,000 ft on climb.

At an altitude between flight level (FL) 180² and FL 200, the pilot observed the illumination of the altitude warning annunciator (Figure 1) and the master warning. The pilot noticed the cabin altitude and aircraft altitude gauges matching and then observed the passenger oxygen masks in the cabin had dropped.

The pilot donned an oxygen mask and commenced an emergency descent to 10,000 ft. During the descent, the pilot was unable to get oxygen due to the oxygen mask's microphone dislodging from its mount. The pilot increased the oxygen flow rate and conducted a return to Jandakot.

Altitude

The engineering inspection revealed the door seal was not inflating correctly.

Figure 1: Pilots are alerted to pressurisation faults via an illuminated alert

Beech 2001 annunciator panel warning				
L ENG FIRE	INVERTER	CABIN DOOR	ALTWARN	R ENG FIRE
L FUEL PRESS			AUX BL AIR FL	R FUEL PRESS
			1 <u></u>	<u> </u>
L CHIP DETECT	L BL AIR FAIL		R BL AIR FAIL	R CHIP DETECT

Source: Operator, annotated by ATSB

Pilot comments

The pilot reported feeling unwell and noted a longer than usual response time for actioning the descent.

Safety action

The operator advised the ATSB that pilots will undergo a revision briefing for pressurisation system faults and recognising the signs of hypoxia. The operator will also ensure pilots check the serviceability of oxygen masks as part of the first flight of day checks.

¹ An automatic bleeding valve or air release valve (ARV) is a plumbing valve used to automatically release trapped air from a heating system.

² Flight level: at altitudes above 10,000 ft in Australia, an aircraft's height above mean sea level is referred to as a flight level (FL). FL 370 equates to 37,000 ft.

Safety message

This incident highlights the importance of ensuring crew oxygen masks are checked for serviceability as part of the daily inspection. This incident further highlights the importance for pilots to have a thorough understanding of the pressurisation system, in particular recognising and reacting to faults in a timely manner. The Beech B200T aircraft alerts the pilot of pressurisation faults with a visual alert only in the form of an illuminated light on the annunciator panel.

Mild hypoxia is not known to impair complex cognition but it has been found to increase fatigue and decrease vigour. Further information about hypoxia can be found in the ATSB research report <u>Depressurisation, Accidents and Incidents Involving Australian Civil Aircraft</u>, and in the Flight Safety Australia article <u>Do not go gentle: the harsh facts of hypoxia</u>.

About this report

Decisions regarding whether to conduct an investigation, and the scope of an investigation, are based on many factors, including the level of safety benefit likely to be obtained from an investigation. For this occurrence, no investigation has been conducted and the ATSB did not verify the accuracy of the information. A brief description has been written using information supplied in the notification and any follow-up information in order to produce a short summary report, and allow for greater industry awareness of potential safety issues and possible safety actions.

General details

Occurrence details

Date and time:	27 September 2022 – 0845 WST		
Occurrence class:	Serious incident		
Occurrence categories:	Depressurisation		
Location:	34 km west south-west of Northam, Western Australia		
	Latitude: 31º 43.425' S	Longitude: 116º 20.538' E	

Aircraft details

Manufacturer and model:	Beech Aircraft Corp B200T		
Type of operation:	Part 138 Aerial work operations		
Activity:	Ferry flight		
Sector:	Turboprop		
Departure:	Jandakot, Western Australia		
Destination:	Kalgoorlie, Western Australia		
Actual destination:	Jandakot, Western Australia		
Persons on board:	Crew – 1	Passengers – 0	
Injuries:	Crew – Nil	Passengers – N/A	
Aircraft damage:	Nil	-	