



Australian Government

Australian Transport Safety Bureau

Aviation Notification Form

Notification Officer:

Section 47F(1)

Phone:

1800 011 034

All orange fields are Mandatory unless information is not available from Reporter

Reporters Name:

Section 47F(1)

Role:

SGT SA Police

Employer:

SA Police

Report date:

17/07/2016

Report time:

1306

Phone:

Section 47F(1)

Registration:

VH-PLM

Flight No:

Aircraft Type:

McDonald Hughes 500 b

Occurrence type:

Crash

Operation Type:

Commercial

Occurrence Date:

17/07/2016

Occurrence Time:

1132

☒ Local☐ UTC

Occurrence location:

Flinders Ranges

State:

SA

Latitude/Longitude:

31 36 45.1 S

138 13 4.1 E

Important for accidents away from aerodromes

Aircraft Operator:

Section 47E(d)

Injuries

| | Fatal | Serious | Minor | Nil |
|------------|-------|---------|-------|-----|
| Crew | | 1 | | |
| Passengers | | 2 | | |
| Ground | | | | |

Damage description:

Reported that craft is relatively intact

Description of occurrence and Additional Information: (Press ALT + ENTER for a new paragraph)

Report of Helicopter crash in the Flinders Rangers near Lake Torrens (Cotabena). Distress beacon activated.

Section 47F(1)

Helicopter was undertaking power line surveying work when suffering engine failure at low altitude. 3 people taken to Adelaide for treatment.

Section 47F(1)

Police reference number 653

Fit Recs Quarantined: ☐ Yes ☐ NoELT Disabled ☐ Yes ☐ NoGuard: ☐ Yes ☐ No

Passed on:

Date

Time

Name

Date

Time

Name

COR:

#####

1315

Section 47F(1)

WebSMS:

Other:

Other:

From: [ATSB International Reporting](#)
To: adrep@icao.int; [NTSB USA National Transport Safety Authority](#)
Cc: [ATSB International Reporting](#)
Subject: FINAL ACCIDENT 201601806 Fuel exhaustion and collision with terrain involving McDonnell Douglas Corporation 369, VH-PLY, 36 km NW Hawker, South Australia, 17 July 2016 [SEC=UNCLASSIFIED]
Date: Wednesday, 8 August 2018 8:31:53 AM
Attachments: [201601806 final report.pdf](#)

Good morning,

Attached is the final investigation report for ATSB occurrence 201601806


Kind regards,

Section 47F(1)

Safety Reporting Officer
Australian Transport Safety Bureau

62 Northbourne Avenue
Canberra ACT 2601

P Section 47F(1) | E Section 47F(1) @atsb.gov.au





Australian Government

Australian Transport Safety Bureau

ICAO ADREP Occurrence Report - 201601806

| State Reporting | Reporting Organisation | State File Number | Date Created | Report Status |
|-----------------|------------------------|-------------------|---------------|---------------|
| Australia | Australia (ATSB) | 201601806 | 8 August 2018 | Data |

| Headline | Occurrence Class | Occurrence Category |
|---|------------------|---------------------|
| ACCIDENT 201601806 Fuel exhaustion and collision with terrain involving McDonnell Douglas Corporation 369, VH-PLY, 36 km NW Hawker, South Australia, 17 July 2016 | Accident | OTHR: Other |

| Local Date Time | UTC Date Time | State/Area Of Occurrence | Location | Latitude | Longitude |
|---------------------------|--------------------------|--------------------------|--|----------|-----------|
| 17 July 2016 10:39 AM CST | 17 July 2016 1:39 AM UTC | Australia | Port Augusta Aerodrome, 25.30° M 107Km | -31.6075 | 138.2237 |

Narrative

On 17 July 2016, at about 1039 Central Standard Time, a McDonnell Douglas Corporation 369D helicopter, registered VH-PLY, experienced fuel exhaustion and a collision with terrain while performing powerline inspections 36 km north-west of Hawker, South Australia. There were three crew on board the helicopter. One pilot in the front left seat, one line-worker in the front right seat and one line-worker in the rear left seat. The three crew members were seriously injured and the helicopter was substantially damaged.

The ATSB found that ground staff mistakenly told the pilot that the aircraft had been refuelled and through distraction, omitted a crosscheck of the fuel quantity before flight. The pilot's monitoring of the fuel in-flight was based on anticipated endurance, which resulted in him not detecting a low fuel level.

The helicopter was operating with an auxiliary fuel tank system, which did not include a fuel quantity indicator. The Civil Aviation Safety Authority and Design Approval Holder provided responses to the ATSB, which indicated that a misunderstanding likely occurred during the design review and approval process. This resulted in the auxiliary fuel tank system approval migrating from the restricted category to the normal category without a fuel quantity indicator.

The ATSB also found the requirements for the development of fuel policy by operators were dispersed throughout the aviation legislation—14 legislative and three guidance material requirements were found—but they did not require the operator to publish procedures for determining fuel on board before and during flight for commercial operators of aircraft not greater than 5,700 kg maximum take-off weight.

Injury Totals

| | Crew | Passenger | Other |
|---------|------|-----------|-------|
| Fatal | 0 | 0 | 0 |
| Serious | 3 | 0 | 0 |
| Minor | 0 | 0 | 0 |
| Nil | 0 | 0 | - |

Occurrence Types

Operational - Fuel related - Exhaustion

Operational - Terrain Collisions - Collision with terrain

Findings

| Finding Type | Safety Factor | Description |
|----------------------------|---|--|
| Contributing safety factor | Organisational influence - Regulatory influences | The Civil Aviation Safety Authority (CASA) accepted that the design advice for the auxiliary fuel tank complied with the relevant requirements of the United States Civil Air Regulation 6. This was within the context of a proposed restricted category approval to permit repositioning flights. However, the response from CASA was likely interpreted by the Design Approver to permit approval in the normal category, which resulted in the auxiliary fuel tank becoming a permanent fit without a fuel quantity indicator. |
| Contributing safety factor | Individual action - Aircraft operation action - Pre-flight inspecting | The pilot omitted to conduct a visual check of the auxiliary fuel tank contents before departure, which resulted in the helicopter departing with insufficient fuel for the planned flight. |
| Contributing safety factor | Individual action - Aircraft operation action - Monitoring and checking | During the flight, the pilot managed the helicopter endurance 'by the clock', which resulted in him not detecting a low fuel level. |
| Other safety factor | Risk control - Procedures | The current legislation does not require commercial operators of aircraft not greater than 5,700 kg maximum take-off weight to provide instructions and procedures for crosschecking the quantity of fuel on board before and/or during flight. This increases the risk that operators in this category will not implement effective fuel policies and training to prevent fuel exhaustion events. |



ICAO ADREP Occurrence Report - 201601806

| | | |
|----------------------------|--|--|
| Contributing safety factor | Individual action - Aircraft operation action - Monitoring and checking | While conducting powerline inspections the helicopter's fuel supply was exhausted, which resulted in a forced landing. |
|----------------------------|--|--|

Safety Recommendations

No Safety Recommendations have been issued in relation to this accident

Mcdonnell Douglas Corp. - 369D, VH-PLY

Aircraft Identification

| Manufacturer / Model | Country Of Registration | Registration Number | Year Of Manufacture | Serial Number |
|--------------------------------|-------------------------|---------------------|---------------------|---------------|
| Mcdonnell Douglas Corp. - 369D | Australia | VH-PLY | 1981 | 110887D |

Aircraft Operation

Section 47E(d)

| Operation Type | Operation Sub Type |
|----------------|-----------------------|
| Aerial Work | Survey / Photographic |

Aircraft Description

| Aircraft Type | Engine Type | Number Of Engines | Weight Category | Maximum Take Off Weight | Landing Gear Type |
|---------------|-------------|-------------------|------------------------|-------------------------|-------------------|
| Helicopter | Turboshaft | 1 | 0-2250 Kg (0-4960 Lbs) | 1360kg | Skid |

Engine Description

| Engine Manufacturer | Engine Model |
|---------------------|--------------|
| ROLLS ROYCE LTD | 250-C20R2 |

Itinerary

| Departed From | Destination | Phase Of Flight |
|-----------------|-----------------|---------------------|
| Port Augusta SA | Port Augusta SA | Maneuvering/airwork |

Person at Controls

| |
|------------------|
| Pilot Flying |
| Pilot in command |

Pilot in command

| Pilot Licence Category | Pilot Licence Type | Total Hours On All | Total Hours On Type | Total Hours On All Last 90 Days | Total Hours On Type Last 90 Days |
|------------------------|--------------------|--------------------|---------------------|---------------------------------|----------------------------------|
|------------------------|--------------------|--------------------|---------------------|---------------------------------|----------------------------------|

Section 47F(1)

VH-PLY Injuries

| | Crew | Passengers |
|---------|------|------------|
| Fatal | 0 | 0 |
| Serious | 3 | 0 |
| Minor | 0 | 0 |
| Nil | 0 | 0 |

OA2016-01806 - Occurrence Details

Occurrence

| | | | | |
|-------------------------|--|---------|-------|-------|
| Logged date | 6/13/2021 12:28:37 AM | | | |
| Status | Approved for release | | | |
| Occurrence class | Accident | | | |
| Highest injury | Serious | | | |
| Occurrence date | 7/17/2016 | | | |
| Occurrence time | 10:39 Cen. Standard Time | | | |
| Public summary | <p>On 17 July 2016, at about 1039 Central Standard Time, a McDonnell Douglas Corporation 369D helicopter, registered VH-PLY, experienced fuel exhaustion and a collision with terrain while performing powerline inspections 36 km north-west of Hawker, South Australia. There were three crew on board the helicopter. One pilot in the front left seat, one line-worker in the front right seat and one line-worker in the rear left seat. The three crew members were seriously injured and the helicopter was substantially damaged. The ATSB found that ground staff mistakenly told the pilot that the aircraft had been refuelled and through distraction, omitted a crosscheck of the fuel quantity before flight. The pilot's monitoring of the fuel in-flight was based on anticipated endurance, which resulted in him not detecting a low fuel level. The helicopter was operating with an auxiliary fuel tank system, which did not include a fuel quantity indicator. The Civil Aviation Safety Authority and Design Approval Holder provided responses to the ATSB, which indicated that a misunderstanding likely occurred during the design review and approval process. This resulted in the auxiliary fuel tank system approval migrating from the restricted category to the normal category without a fuel quantity indicator. The ATSB also found the requirements for the development of fuel policy by operators were dispersed throughout the aviation legislation—14 legislative and three guidance material requirements were found—but they did not require the operator to publish procedures for determining fuel on board before and during flight for commercial operators of aircraft not greater than 5,700 kg maximum take-off weight.</p> | | | |
| Property damage | Unknown | | | |
| Property damage details | | | | |
| Worst accident outcome | Major accident | | | |
| Defence effectiveness | Not effective | | | |
| Risk rating | High (500) | | | |
| ERC justification | | | | |
| TSI reportable | Immediately reportable | | | |
| Ground injuries | Fatal | Serious | Minor | Total |
| | 0 | 0 | 0 | 0 |

Location

| | |
|-----------|--|
| Location | Port Augusta Aerodrome, 25.30° M 107Km |
| Latitude | -31.60750000 |
| Longitude | 138.22370000 |
| State | SA |
| Country | Australia |

Aircraft

| | |
|-----------------------------|--------------------------------------|
| Registration | VH-PLY |
| Type | Helicopter |
| Manufacturer | MCDONNELL DOUGLAS HELICOPTER COMPANY |
| Model | 369D |
| Engine type | Turboshaft |
| Engine manufacturer | ROLLS ROYCE CORPORATION |
| Engine model | 250-C20R2 |
| Number of engines | 1 |
| Landing gear type | Skid |
| Fuel type | Kerosene |
| Year of manufacture | 1981 |
| Amateur built | |
| Maximum takeoff weight (kg) | 1360 |
| ELT Type | |
| ELT Fitted | No |
| ELT Activated | No |

Airspace

| | |
|--------------------|------------|
| Controlling agency | Aust Civil |
| ATS service type | Other |
| ATS position | Other |
| Airspace class | G |
| Airspace type | OCTA |

Operation

| | |
|---------------|--------|
| Registration | VH-PLY |
| Flight number | |

Section 47E(d)

| | |
|-----------------------|---------------------------------------|
| Related runway | |
| Phase of flight | Manoeuvring/airwork |
| PIC status | Employee |
| Pilot flying role | Pilot in command |
| Departure aerodrome | Port Augusta Aerodrome [YPAG] |
| Destination aerodrome | Port Augusta Aerodrome [YPAG] |
| Actual landing | |
| Aerodrome proximity | Off aerodrome > 10 km |
| Operation type | Aerial Work |
| Operation subtype | Survey / Photographic - (Aerial Work) |
| Activity group | General aviation / Recreational |
| Activity type | Aerial work |
| Activity subtype | Pipeline / powerline surveying |
| Flight rules | VFR |
| Flight conditions | VMC |
| Altitude type | AMSL (above mean sea level - ft) |
| Altitude | Exactly |
| Exact altitude | 80 |
| Other information | |

Occurrence category

| | |
|--------------|--------------------------------------|
| Registration | VH-PLY |
| Level 1 | Operational Operational |
| Level 2 | Fuel related Terrain collisions |
| Level 3 | Exhaustion Collision with terrain |

Damage level and injuries

| | | | | |
|-----------------------|--------------|----------------|--------------|--------------|
| Registration | VH-PLY | | | |
| Injury level | Fatal | Serious | Minor | Total |
| Crew | | 3 | | 3 |
| Passengers | | | | |
| Aircraft damage level | Substantial | | | |
| Post impact fire | No | | | |
| Damage description | | | | |

Weather and environment

| | |
|--------------------------------|-----------|
| Cloud cover | Sky clear |
| Visibility (km) | |
| Light conditions | Daylight |
| Wind direction | SSE |
| Average wind speed (kts) | 4 |
| Cloud base (ft) | |
| Visibility reduced by | None |
| Turbulence conditions | Nil |
| Icing conditions | Nil |
| Precipitation type | Nil |
| Precipitation intensity | Nil |
| QNH | |
| Outside temperature | |
| Light and variable (windspeed) | No |
| Maximum wind speed (gust) | |
| Dew point | |
| CAVOK | |
| Effective cloud ceiling | |
| Weather phenomena | |

Safety factor

| | |
|---------|--|
| Level 1 | |
| Level 2 | |
| Level 3 | |