



Australian Government

Australian Transport Safety Bureau

Foreign object debris involving Airbus A380, VH-OQK

Sydney Airport, New South Wales, on 9 January 2026



ATSB Transport Safety Report

Aviation Occurrence Investigation (Defined)

AO-2026-004

Final – 17 August 2026

Cover photo: Aircraft operator, annotated by the ATSB

Released in accordance with section 25 of the *Transport Safety Investigation Act 2003*

Publishing information

Published by: Australian Transport Safety Bureau
Postal address: GPO Box 321, Canberra, ACT 2601
Office: 12 Moore Street, Canberra, ACT 2601
Telephone: 1800 020 616, from overseas +61 2 6257 2463
Accident and incident notification: 1800 011 034 (24 hours)
Email: atsbinfo@atsb.gov.au
Website: atsb.gov.au

© Commonwealth of Australia 2026



Ownership of intellectual property rights in this publication

Unless otherwise noted, copyright (and any other intellectual property rights, if any) in this publication is owned by the Commonwealth of Australia.

Creative Commons licence

With the exception of the Commonwealth Coat of Arms, ATSB logo, and photos and graphics in which a third party holds copyright, this report is licensed under a Creative Commons Attribution 4.0 International licence.

The CC BY 4.0 licence enables you to distribute, remix, adapt, and build upon our material in any medium or format, so long as attribution is given to the Australian Transport Safety Bureau.

Copyright in material used in this report that was obtained from other agencies, private individuals or organisations, belongs to those agencies, individuals or organisations. Where you wish to use their material, you will need to contact them directly.

Acknowledgement of Country and Traditional Owners

The Australian Transport Safety Bureau acknowledges the traditional owners of country throughout Australia, and their continuing connection to land, sea and community. We pay our respects to them and their cultures, and to elders both past and present.

Investigation summary

What happened

On 7 January 2026, an Airbus A380-842 aircraft, registered VH-OQK and operated by Qantas Airways Limited, arrived at Sydney Airport, New South Wales, from Los Angeles International Airport, United States. Following arrival, maintenance was conducted on the aircraft's air conditioning system, which required access to an internal area of the left wing.

After the conduct of this maintenance, a work light was inadvertently left in the aircraft wing and the aircraft departed later in the afternoon on a scheduled flight to Dallas Fort Worth International Airport (DFW), United States. The work light was subsequently found following the aircraft's return to Sydney Airport from DFW on 9 January 2026.

What the ATSB found

The ATSB found that the occurrence resulted from a breakdown in foreign object control and tool accountability processes during and after maintenance. Following maintenance on the air conditioning system, the maintainers did not identify that a work light had remained in the left wing during their foreign object clearance inspections. In addition, while returning the tools, the maintainer did not identify that the work light had not been returned and the unreturned tool check at the end of the shift also did not identify the unreturned light.

The ATSB also found that tool control procedural defences did not prevent the aircraft from being released to service with the unaccounted tool. The licensed aircraft maintenance engineer issued a certificate of release to service (CRS) despite the work light being unaccounted for. Contributing to this, the operator's maintenance information system did not provide a prompt or control to alert the certifier to the unreturned tool or the unactioned unreturned tool report prior to CRS issue. This allowed the omission to go undetected.

What has been done as a result

Following the occurrence, Qantas released a safety directive to address changes to its tooling control processes and procedures. It has also formed a tooling working group to work on various initiatives, including new technologies, to improve tool control across its various maintenance locations.

Safety message

Foreign object debris and damage poses a significant risk to the safe operation of aircraft. To mitigate this risk, regulations, procedures and training have been developed and refined, particularly to manage the introduction of foreign objects during maintenance. Central to these controls is the effective application of tool control, which serves as a fundamental defence against human error.

However, this occurrence demonstrates that even well-established processes are vulnerable when they rely solely on consistent human performance. Maintenance tasks are often conducted in challenging environments and under operational pressures, and human performance can vary accordingly. Tool control systems and procedures must therefore be designed to account for this variability, incorporating robust checks and safeguards capable of detecting and recovering from errors, particularly during routine or repetitive tasks where the likelihood of oversight may increase.

Contents

Investigation summary	i
The occurrence	1
Day 1 – 7 January 2026	1
Day 2 – 8 January 2026	2
Day 3 – 9 January 2026	3
Context.....	5
Conduct of maintenance	5
Maintenance team and work environment	5
Aircraft system	5
Maintenance task and conditions	6
Tooling	7
Tool issue and control	8
Certification responsibilities	9
Related occurrence	9
AO-2024-006	9
Safety analysis	10
Foreign object clearance inspections and tool return	10
Unreturned tool report check	11
Findings	12
Contributing factors	12
Other factors that increased risk	12
Safety issues and actions	13
General details	15
Glossary.....	16
Sources and submissions.....	17
About the ATSB	18

The occurrence

On 7 January 2026, an Airbus A380-842 (A380) aircraft, registered VH-OQK and operated by Qantas Airways Limited, arrived at Sydney Airport, New South Wales, from Los Angeles International Airport (LAX), United States (US) with 26 crew members and 485 passengers on board. As the aircraft was scheduled to remain on the ground for several hours, maintenance planning had arranged some time for minor defect corrections, including maintenance on the air conditioning system, prior to the aircraft departing on a scheduled flight to Dallas Fort Worth International Airport (DFW), US.

Day 1 – 7 January 2026

The maintenance team at the Sydney International Terminal commenced their shift at 0500 local time, with the A380 crew comprised of one licensed aircraft maintenance engineer (LAME) and 3 aircraft maintenance engineers (AMEs). During the morning, that crew conducted multiple aircraft tows, including unscheduled tows of an Airbus A330 and a Boeing 747-400. At 0718, VH-OQK arrived at Bay 10 from LAX, and the maintenance crew commenced engine oil replenishments and post-arrival inspections. Due to the bay being required for another aircraft, at 0815 the aircraft was towed to the Qantas Jet Base north run-up bay (Figure 1). This tow took approximately 30 minutes to complete.

Figure 1: Sydney Airport key locations



Source: Google Earth, annotated by the ATSB

Following the aircraft tow, the LAME and AME 3 commenced work in the cabin to rectify several minor defects. The cleaning crew were also on board at the time, and as the aircraft air conditioning system was inoperative due to required maintenance, there was added pressure on the LAME to restore functionality due to high ambient temperatures (see the section titled *Weather*).

Concurrently, the LAME assigned the 2 AMEs (AME 1 and AME 2) the maintenance task on the air conditioning system. This involved changing an outlet temperature sensor on the air generation unit (AGU) secondary heat exchanger within the left wing. To complete the task, AME 1 signed out tools from the Hangar 191 (Figure 1) tool crib, including a toolbox, screw guns, and a work light. The toolbox and screw guns were signed out against the specific task, and the work light was signed out against the aircraft registration (see the section titled *Tool issue and control*). At the commencement of the task, an under-wing access panel was removed to allow the maintainers to enter the wing (Figure 4). AME 2 completed the temperature sensor change while AME 1 provided support by passing the required tooling. This included the work light, that was placed inside the wing to illuminate the area.

Following the completion of the temperature sensor change, AME 2 selected the work light power to OFF as they exited the wing. The LAME subsequently conducted an inspection of the work done on the sensor and then proceeded to the flight deck with both AMEs to conduct a test of the air conditioning system. The test required auxiliary power unit (APU) operation, however, the APU unexpectedly failed during start-up. Troubleshooting identified a requirement to bleed the APU fuel system, and AME 1 was sent to obtain an elevated work platform and the required tooling from Hangar 191, resulting in a delay of approximately 30 minutes.

After the APU was successfully started and the testing of the air conditioning system was completed, the LAME returned to the wing and completed a foreign object debris (FOD) clearance inspection with the use of a torch. Subsequently, AME 2 and AME 3 reinstalled the previously removed access panel and AME 1 returned the elevated work platform and tools to the Hangar 191 tool crib.

There was a requirement for the aircraft to be at the departure bay earlier than usual. Consequently, this reduced the time available for maintenance on the aircraft. At approximately 1200, the aircraft was towed back to Bay 9, arriving at around 1245. Shortly after, the LAME departed the aircraft to deal with an unexpected engine maintenance policy change, which required them to return to the office to use the main computer terminal rather than their iPad. While they were away, the AMEs continued departure preparation, including refuelling the aircraft. The LAME subsequently returned to the aircraft while pre-flight preparations were being performed.

At 1321, the LAME completed the maintenance documentation work package and issued a certificate of release to service (CRS) (see the section titled *Certification responsibilities*). Around 1430, the crew had their first dedicated break since commencing their shift and at 1457, VH-OQK, operating as QF7, departed for DFW.

Day 2 – 8 January 2026

On 8 January 2026, VH-OQK arrived in DFW. Maintenance was carried out on the aircraft by a contracted external maintenance organisation and a CRS was issued. This

maintenance was carried out under the maintenance organisation's separate Part 145 approval and did not use the Qantas tool control system. Later that day, the aircraft departed DFW, as QF8, and arrived at Sydney International Airport on 9 January 2026 at 0655.

Day 3 – 9 January 2026

Later that morning after the aircraft had landed, the Hangar 191 tool crib operator reviewed an unreturned tool report, which provided a status of tools currently signed out of the tool crib. They identified that 2 days earlier, a work light had been signed out against VH-OQK and had not been returned. The tool crib operator notified the duty maintenance manager of the missing tool, who later contacted AME 1, who had signed out the tool. AME 1 could not confirm if the work light had been returned and raised the possibility that it remained in the aircraft wing.

A lost tool search was initiated, and the missing work light was subsequently located inside the wing of the aircraft (Figure 2). No adverse consequences, structural damage, or system disruptions resulted from the work light remaining in the wing.

Figure 2: Work light within wing of aircraft



Source: Aircraft operator, annotated by the ATSB

Context

Conduct of maintenance

Maintenance team and work environment

The A380 maintenance team at the Sydney International Terminal (SIT) usually consisted of 4 maintainers: 1 licensed aircraft maintenance engineer (LAME) and 3 aircraft maintenance engineers (AMEs) involved in the receipt and dispatch of Airbus A380 (A380) aircraft, in addition to other aircraft tasking, depending on staffing levels. The team worked a roster that consisted of 4 days on, 2 day shifts followed by 2 night shifts, and 5 days off. On 7 January 2026, the maintenance team had commenced their first day shift following their rostered off period.


Prior to the start of the shift, the maintenance planning department assigned maintenance tasks to be completed while the aircraft was planned to be on the ground. However, the SIT maintenance work environment was dynamic, consistent with a flightline operation supporting the airline's schedule, requiring continual adjustments to the planned maintenance tasks. The plan could be further adversely affected when unplanned maintenance issues arose, introducing time pressures and competing priorities. These conditions made it difficult to schedule work tasks and rest breaks at consistent times throughout the shift.

Additionally, staffing levels and the availability of personnel with specific required qualifications could further impact task allocation and workload management. At the commencement of the shift at 0500, only the LAME and AME 1 were assigned to the A380 maintenance team. Both were highly experienced, having worked for the operator as maintainers for 37 years and 22 years respectively. AME 2 and AME 3 were later assigned from the hangar maintenance team. AME 2, who conducted the temperature sensor change, was an experienced maintainer, and had worked for the operator for approximately one year.

Aircraft system

The A380 air conditioning system consists of 2 air generation units (AGUs), also referred to as 'air conditioning packs' (Figure 3). Pack 1 is in the inboard left wing and pack 2 in the inboard right wing. The purpose of each AGU is to cool hot engine bleed air before it is distributed for use throughout the aircraft. To achieve this, the AGU incorporates a primary and secondary heat exchanger.

Each heat exchanger is a radiator-like device that reduces the temperature of the bleed air by passing it through a series of small passages while cooler ambient air flows around them. This process allows heat to be transferred from the hot bleed air to the surrounding airflow, lowering the bleed air temperature without the air streams mixing.

Figure 3: Air generation unit


Source: Airbus aircraft maintenance manual, annotated by the ATSB

Maintenance task and conditions

The maintenance task required a change of the outlet temperature sensor on the secondary heat exchanger of the left AGU. The removal of an underwing inboard leading edge access panel (Figure 4) is required to gain access into the wing where the AGU is positioned. A work platform is required to access and remove the panel due to the height of the aircraft's underside and wing.

The area inside the wing was a confined workspace with limited ambient light, therefore requiring a light source to conduct work (Figure 2). There was space for the maintainers to enter the wing towards the leading edge, however space to work was more restrictive nearer to the AGU. AME 1 reported the workspace inside the wing was warm and stuffy due to the high outside air temperature and residual heat from bleed ducts within the wing. They further recalled that, following the maintenance within the wing, AME 2 was visibly sweating and wanted to get out for a drink of water.

Figure 4: Aircraft access panel location



Source: Airbus aircraft maintenance manual, annotated by the ATSB

Weather

Sydney Airport recorded weather data from 7 January 2026 showed the temperature was 27°C at 0900 with scattered cloud cover,¹ reducing over the morning. At 1130, the temperature had climbed to 30°C with no cloud cover.

Tooling

The tooling required for the temperature sensor change consisted of a work light, and a combination spanner and a pair of multigrip pliers contained within the signed-out toolbox.

The work light, as shown in Figure 2, was a Makita corded and cordless LED work light capable of being powered by the cord or by attaching a compatible rechargeable battery to allow for portability. During the replacement of the temperature sensor, the work light was powered with an attached battery. The dimensions of the work light were 214 mm (length), 261 mm (width) and 328 mm (height). The work light was predominantly black in colour with a teal backing.

The work light power was found in the off position; however, when turned on, the light functioned normally, indicating that the battery retained sufficient charge.

¹ Cloud cover: in aviation, cloud cover is reported using words that denote the extent of the cover – 'scattered' indicates that cloud is covering between a quarter and a half of the sky.

Tool issue and control

Tool control is a fundamental aspect of aviation maintenance in addition to being a requirement within the Civil Aviation Safety Regulations. Procedures and processes to control tools were required and intended to track tools used on aircraft and the individual using the tools to ensure they were not left on an aircraft.

The process for tool issue and control within the Qantas Engineering maintenance environment commenced when maintenance tasks were assigned within the maintenance information system known as Maintenix (MXI). This system provided maintainers with details related to maintenance tasks, aircraft parts and the tooling required to complete the task. Each task was identified by a unique barcode.

Tooling was centrally stored in a tool crib and a tool crib operator provided oversight over the issuing and returning of the tools.² The tooling was required to be signed out to the individual maintainer and linked to the specific aircraft or aircraft task by scanning the barcode on the specific tools against the task barcode or the barcode for the aircraft registration and the individual. This ensured the signed-out tooling was recorded in the maintenance information system. The status of signed-out tooling was viewable using an unreturned tool report that identified any tooling signed out to a task, a maintainer or an aircraft registration. However, the report gave a status at a given time it was generated and did not retain a permanent record.

Upon completion of the maintenance task, the maintainer conducting the task was responsible for ensuring all tooling was removed from the aircraft. In addition, a mandatory clearance inspection was required to be conducted by the certifier to confirm that the work area, and therefore aircraft, was free from tools or foreign objects.

Only once the clearance inspection was completed, and tooling accounted for, could the maintenance task proceed to certification. The use of the unreturned tool report was the preferred means to account for tools prior to certifying for the maintenance and issuing a certificate of release to service (CRS). While this procedure was well known to the LAME, they had later realised that on this occasion they had not generated and reviewed the unreturned tool report for the aircraft prior to issuing the CRS.

If there were tools identified on the unreturned tool report at this stage, the procedure stated:

If there is any tooling listed on the AMO [approved maintenance organisation] UTR [unreturned tool report] then the whereabouts of this tooling needs to be confirmed as not posing a risk.

In addition, the operator's company and personal tool policy stated:

The Duty Maintenance Managers, Shift Managers, Maintenance Supervisors / Crew Leaders or Maintenance Airworthiness & Safety Controllers (MASC) shall ensure maintenance employees under their control carry out a full tooling inventory check at the end of shift.

Any tools identified as unaccounted for became 'lost tools' and a search procedure was to be followed to locate and retrieve the tools.

² There were also allowances in the procedures for tooling to be issued without a tool crib employee present.

There was no requirement for the tool crib operators to use the unreturned tool report during, or at the end of, the shift, to account for tools that had not been returned. The tool crib employee advised that the unreturned tool report was used to gain situation awareness of signed out tools, run either at the start of a shift or every 48 hours.

Certification responsibilities

Under the Civil Aviation Safety Regulations (CASRs) Part 42.330, the individual who carries out the maintenance task was required to remove any tools or equipment before a CRS was issued for the aircraft. The Civil Aviation Safety Authority (CASA) provided acceptable means of compliance (AMC) to regulation 42.330, which included the use of a shadow board,³ electronic tool and equipment management system, or tool and equipment audit system to ensure all tooling has been removed from the aircraft.

To meet the CASRs for the conduct and certification of maintenance, the operator's procedure for the *Certificate of release to service* detailed that:

A CRS must be issued following any maintenance activity and related maintenance certification. This includes any certified entry in the logbooks or the MIS.

Part of the maintainer's responsibilities when issuing a CRS included:

Verify that all tools and equipment have been removed from the aircraft and accounted for (CASR 42.330). AMO Unreturned Tool Report are available from the MIS and should be used.

Related occurrence

[AO-2024-006](#)

On 6 December 2023, an Airbus A380-842 aircraft, registered VH-OQI and operated by Qantas Airways Limited, was undergoing a 3-day scheduled maintenance check at Los Angeles International Airport (LAX), United States. On day one of the maintenance check, during a scheduled borescope inspection of the outboard left engine, a tool was left in the engine inlet.

On 1 January 2024, the aircraft returned to the LAX maintenance facility for a 3-day scheduled maintenance check, where the missing tool was discovered in the outboard left engine low-pressure compressor. The aircraft had flown 34 cycles totalling 293.74 hours with the tool in the outboard left engine.

³ A shadow board is a visual tool control system where each tool has a clearly marked position, allowing users to quickly identify missing items and ensuring all tools are returned and accounted for.

Safety analysis

Foreign object clearance inspections and tool return

At the conclusion of the maintenance task to change the outlet temperature sensor on the air generation unit inside the left wing of the Airbus A380, aircraft maintenance engineer (AME) 1, AME 2 and the licensed aircraft maintenance engineer (LAME) did not observe the work light that remained in the left wing during their foreign object clearance inspections. It's likely that the work light was not identified in part due to:

- The work light had been selected off when the crew went to the cockpit to run the air conditioning unit.
- The confined workspace within the wing with low lighting combined with the work light colours making it difficult to visually identify.
- The high temperature within the confined workspace likely reducing the time spent conducting the clearance inspections.

Contributing factor

The aircraft maintenance engineers and licensed aircraft maintenance engineer did not observe a work light that remained in the left wing during their foreign object clearance inspections following maintenance on the aircraft air conditioning system.

Given the unplanned interruption and additional maintenance activity related to the auxiliary power unit (APU), it is likely that when AME 1 later returned the tools to the tool crib, they had reduced ability to recall all items used during the outlet temperature sensor replacement. Additionally, this ability to recall the tools used in the task was likely also influenced by the work light not being a tool physically used in the task, but rather a passive tool used to illuminate the workspace.

Contributing factor

In part due to the type of tool used during the temperature sensor change, and the follow-on troubleshooting needed on the auxiliary power unit, the aircraft maintenance engineer returned the tools to the tool crib without realising that the work light was still signed out and not returned.

At the conclusion of the shift, neither AME 1 or their supervisor identified that the work light had not been returned and remained signed out to AME 1. The ATSB was unable to identify if the unreturned tool report was reviewed at the conclusion of the shift or the light was missed during the review. While the CRS had already been issued and the aircraft had departed for Dallas Fort Worth International Airport (DFW) prior to the end of the shift, the end of shift tool return check represented another opportunity where the work light could have been identified as missing and removed while on the ground at DFW.

Other factor that increased risk

At the end of the shift, it was not identified that a tool had not been returned and remained signed out to the aircraft maintenance engineer.

Unreturned tool report check

At the completion of maintenance, following the clearance inspections and prior to issuing the certificate of release to service (CRS), the unreturned tool report was the preferred means for the certifier to account for all tooling used during maintenance. While this process was well known and routinely performed by the LAME, they later realised that on this occasion they had not generated and reviewed the unreturned tool report for the aircraft prior to issuing the CRS.

This omission, within a routinely performed task, was likely influenced in part by attention being diverted during the departure preparations for the aircraft, whereby the LAME had an unexpected maintenance task, and they were supervising the AMEs while concurrent pre-flight activities were being conducted. Consequently, the CRS was issued with the work light unaccounted for and the aircraft flew 2 sectors with the work light in the left wing.

Contributing factor

The licensed aircraft maintenance engineer issued a certificate of release to service with a tool unaccounted for. As a result, the aircraft flew 2 sectors with the work light in the left wing.

The action of checking the unreturned tool report, prior to issuing a CRS, was documented within the engineering procedures and was well known to the LAME. This procedure did, however, create the requirement for engineers to manually initiate and review the unreturned tool report within the maintenance information system (MXI). This made the process vulnerable to omissions whereby a CRS could be issued without review of the unreturned tool report. Furthermore, the design of the MXI system meant that there was no way to prompt or identify to the certifier that either tools were still signed out to the aircraft or that the unreturned tool report had not been reviewed.

Contributing factor

Qantas Engineering's maintenance information system did not have an automated way to identify to the certifier, prior to issuing the certificate of release to service, that tools used on the aircraft were unreturned or that the unreturned tool report had not been actioned. (Safety issue)

Findings

ATSB investigation report findings focus on safety factors (that is, events and conditions that increase risk). Safety factors include 'contributing factors' and 'other factors that increased risk' (that is, factors that did not meet the definition of a contributing factor for this occurrence but were still considered important to include in the report for the purpose of increasing awareness and enhancing safety). In addition 'other findings' may be included to provide important information about topics other than safety factors.

Safety issues are highlighted in bold to emphasise their importance. A safety issue is a safety factor that (a) can reasonably be regarded as having the potential to adversely affect the safety of future operations, and (b) is a characteristic of an organisation or a system, rather than a characteristic of a specific individual, or characteristic of an operating environment at a specific point in time.

These findings should not be read as apportioning blame or liability to any particular organisation or individual.

From the evidence available, the following findings are made with respect to the foreign object debris involving Airbus A380, VH-OQK, at Sydney Airport, New South Wales, on 9 January 2026.

Contributing factors

- The aircraft maintenance engineers and licensed aircraft maintenance engineer did not observe a work light that remained in the left wing during their foreign object clearance inspections following maintenance on the aircraft air conditioning system.
- In part due to the type of tool used during the temperature sensor change, and the follow-on troubleshooting needed on the auxiliary power unit, the aircraft maintenance engineer returned the tools to the tool crib without realising that the work light was still signed out and not returned.
- The licensed aircraft maintenance engineer issued a certificate of release to service with a tool unaccounted for. As a result, the aircraft flew 2 sectors with the work light in the left wing.
- **Qantas Engineering's maintenance information system did not have an automated way to identify to the certifier, prior to issuing the certificate of release to service, that tools used on the aircraft were unreturned or that the unreturned tool report had not been actioned.** (Safety issue)

Other factors that increased risk

- At the end of the shift, it was not identified that a tool had not been returned and remained signed out to the aircraft maintenance engineer.

Safety issues and actions

Central to the ATSB’s investigation of transport safety matters is the early identification of safety issues. The ATSB expects relevant organisations will address all safety issues an investigation identifies.

Depending on the level of risk of a safety issue, the extent of corrective action taken by the relevant organisation(s), or the desirability of directing a broad safety message to the aviation industry, the ATSB may issue a formal safety recommendation or safety advisory notice as part of the final report.

All of the directly involved parties are invited to provide submissions to this draft report. As part of that process, each organisation is asked to communicate what safety actions, if any, they have carried out or are planning to carry out in relation to each safety issue relevant to their organisation.

The initial public version of these safety issues and actions will be provided separately on the ATSB website on release of the final investigation report, to facilitate monitoring by interested parties. Where relevant, the safety issues and actions will be updated on the ATSB website after the release of the final report as further information about safety action comes to hand.

Unreturned tool report

Safety issue description

The operator's maintenance information system did not have an automated way to identify to the certifier, prior to issuing the certificate of release to service, that tools used on the aircraft were unreturned or that the unreturned tool report had not been actioned.

Issue number:	AO-2026-004-SI-01
Issue owner:	Qantas Airways Limited
Transport function:	Aviation: Maintenance
Current issue status:	Open – Safety action pending
Issue status justification:	The ATSB welcomes the action taken by Qantas but notes that it may still permit an aircraft to be released to service without an unreturned tool check being completed. However, it also acknowledges the ongoing work Qantas is doing in this area and is satisfied that when this project is complete it will adequately address the safety issue.

Proactive safety action taken by Qantas

Action number:	AO-2026-004-PSA-01
Action organisation:	Qantas Airways Limited
Action status:	Monitor

Following the occurrence, Qantas released a safety directive on 18 February 2026 to address changes to its tooling control processes and procedures. Most notably, the safety directive required that prior to issuing a CRS, certifiers were to complete a ‘pre CRS tooling check’ task within the maintenance information system, Maintenix (MXI). This requires the unreturned tool report to be generated, reviewed and attached to the

task within MXI. Importantly, this means that a CRS cannot be issued until the tooling check is complete in MXI.

Qantas also advised the ATSB that it has formed a tooling working group to work on various initiatives, including new technologies, to improve tool control across its various maintenance locations. This group is due to make recommendations in the next 2–3 months and Qantas will continue to keep the ATSB updated on progress.

General details

Occurrence details

Date and time:	09 January 2026 15:00 AUS Eastern Daylight-saving Time	
Occurrence class:	Incident	
Occurrence categories:	Foreign Object Damage / Debris	
Location:	Sydney Airport	
	Latitude: 33.9461° S	Longitude: 151.1772° E

Aircraft details

Manufacturer and model:	AIRBUS INDUSTRIE A380-842	
Registration:	VH-OQK	
Operator:	Qantas Airways Limited	
Serial number:	63	
Type of operation:	Part 121 Australian air transport operations - Larger aeroplanes-Standard Part 121	
Activity:	Commercial air transport-Scheduled-International	
Departure:	Sydney Airport, New South Wales	
Destination:	Dallas/Fort Worth International Airport, United States	
Persons on board:	Crew – 26	Passengers – 485
Injuries:	Crew – 0	Passengers – 0
Aircraft damage:	Nil	

Glossary

AGU	Air generation unit
AMC	Acceptable means of compliance
AME	Aircraft maintenance engineer
APU	Auxiliary power unit
CASA	Civil Aviation Safety Authority
CASR	Civil Aviation Safety Regulations
CRS	Certificate of Release to Service
DFW	Dallas Fort Worth International Airport
FOD	Foreign object debris
LAME	Licenced aircraft maintenance engineer
LAX	Los Angeles International Airport
LED	Light-emitting diode
MXI	Maintenix
SIT	Sydney International Terminal
US	United States

Sources and submissions

Sources of information

The sources of information during the investigation included:

- Qantas Airways Limited
- the aircraft maintenance engineers directly involved in the task
- the tool crib operator who identified the missing tool.

Submissions

Under section 26 of the *Transport Safety Investigation Act 2003*, the ATSB may provide a draft report, on a confidential basis, to any person whom the ATSB considers appropriate. That section allows a person receiving a draft report to make submissions to the ATSB about the draft report.

A draft of this report was provided to the following directly involved parties:

- Qantas Airways Limited
- the aircraft maintenance engineers directly involved in the task
- the tool crib employee who identified the missing tool
- Civil Aviation Safety Authority.

Submissions were received from:

- an aircraft maintenance engineer directly involved in the task
- Qantas Airways Limited.

The submissions were reviewed and, where considered appropriate, the text of the report was amended accordingly.

About the ATSB

The **Australian Transport Safety Bureau** is Australia's national transport safety investigator. Established by the *Transport Safety Investigation Act 2003* (TSI Act), the ATSB is an independent statutory agency of the Australian Government and is governed by a Commission. The ATSB is entirely separate from transport regulators, policy makers and service providers.

The ATSB's function is to improve transport safety and public confidence, in aviation, marine and rail, through:

- the independent 'no blame' investigation of transport accidents and other safety occurrences
- safety data recording, analysis, and research
- influencing safety action.

The ATSB's sole focus is the prevention of future accidents and the improvement of transport safety, and prioritises investigations that have the potential to deliver the greatest public benefit.

The ATSB performs its functions in accordance with the provisions of the TSI Act and Regulations and, where applicable, international agreements.

Purpose of safety investigations

The objective of an ATSB safety investigation is to improve transport safety through:

- identifying safety issues for action by organisations with the responsibility for managing that safety risk
- influencing safety action through engaging with stakeholders, communicating findings, and fostering awareness of safety issues and concerns.

In accordance with the TSI Act, the ATSB does not investigate for the purpose of taking administrative, regulatory or criminal action, and cannot apportion blame, assist in determining liability, or, as a general rule, assist in court proceedings.

About ATSB reports

ATSB safety investigation reports are developed in accordance with ATSB procedures and guidelines, and with regard to applicable international standards and instruments.

Reports must include factual material of sufficient weight to support the investigation's analysis and findings. At all times the ATSB endeavours to balance the use of material that could imply adverse comment with the need to properly explain what happened, and why, in a fair and unbiased manner.

An explanation of ATSB terminology used in this report is available on the [ATSB website](#).