


M. W. ...

**BUREAU OF AIR SAFETY INVESTIGATION
REPORT**

**Boeing 747-400 and
Piper PA31-350
Breakdown in separation
near Mona Vale, NSW
24 November 1992**

Report B/926/3123



BASi

Bureau of Air Safety Investigation



**DEPARTMENT OF
Transport**

Department of Transport
Bureau of Air Safety Investigation

INVESTIGATION REPORT
B/926/3123

**Boeing 747-400 VH-OJG
and
Piper PA31-350 VH-WGG
Breakdown in separation near
Mona Vale, New South Wales
24 November 1992**

BASi
Bureau of Air Safety Investigation

Released by the Director of the Bureau of Air Safety Investigation
under the provisions of Air Navigation Regulation 283

When the Bureau makes recommendations as a result of its investigations or research, safety (in accordance with its charter), is its primary consideration. However, the Bureau fully recognises that the implementation of recommendations arising from its investigations will in some cases incur a cost to the industry.

Readers should note that the information in BASI reports is provided to promote aviation safety: in no case is it intended to imply blame or liability.

ISBN 0 642 20226 5

March 1994

This report was produced by the Bureau of Air Safety Investigation (BASI), PO Box 967, Civic Square ACT 2608.

The Director of the Bureau authorised the investigation and the publication of this report pursuant to his delegated powers conferred by Air Navigation Regulations 278 and 283 respectively. Readers are advised that the Bureau investigates for the sole purpose of enhancing aviation safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purpose.

As BASI believes that safety information is of greatest value if it is passed on for the use of others, copyright restrictions do not apply to material printed in this report. Readers are encouraged to copy or reprint for further distribution, but should acknowledge BASI as the source.

<i>Aircraft type</i>	Boeing B747-400	Piper PA31-350
<i>Registration</i>	VH-OJG	VH-WGG
<i>Nominated/apparent class of operation</i>	Scheduled International Passenger Service	Scheduled Passenger Service
<i>Degree of damage to aircraft</i>	Nil	Nil
<i>Location</i>	Near Mona Vale NSW 33° 52' S 151° 14' E	
<i>Date and time</i>	24 November 1992, 0727 hours*	
<i>Departure point</i>	Los Angeles USA	Williamtown NSW
<i>Departure time</i>	Unknown	0703 hours
<i>Destination</i>	Sydney NSW	Canberra ACT
Crew:	Pilot in command	Pilot in command
– <i>Class of licence</i>	ATPL	CPL
– <i>Hours on type</i>	Not known	Not known
– <i>Total hours</i>	Not known	2,500 approx.
– <i>Degree of injury</i>	Nil	Nil
Others persons involved:		
– <i>On board aircraft</i>	Nil	Nil
– <i>ATS personnel</i>		Nil

*All times are Eastern Standard Summer Time which equates to Co-ordinated Universal Time + 11 hours.

1. FACTUAL INFORMATION

VH-WGG departed Williamtown at 0703 hours and proceeded to track via the 015 radial of the Sydney VOR at 8,000 ft. The pilot contacted the Sydney Departures North controller 28 NM from Sydney and the radar identification was passed to the Approach North controller, who raised a 'shrimp boat' (a small piece of plastic which adheres to the radar screen and allows the controller to write pertinent information on it for his/her reference) and placed it on the radar screen next to the radar return of VH-WGG. The shrimp boat was not positionally updated nor was it annotated to indicate to which aircraft it was referring.

When an aircraft passes overhead Sydney, its track impinges on all four sectors of approach/departures airspace and two flight progress strips (FPSs) are raised, one for approach use and one for departures. These FPSs are pink in colour to enable them to stand out from the other FPSs in use. The aircraft is identified by the controller in whose airspace it enters and the progress is then monitored by all four controllers by updating the position of their 'shrimp boats' on the radar screen and placing the pink FPS in the central (active) strip bay.

As the track of VH-WGG affected all four approach/departures controllers each pair had a pink strip for information purposes. In the case of the two approach controllers this strip should have been placed in the central sequence bay but, because of the number of arrival strips being processed in a busy sequence, this was not done and the strip was placed in the Approach South bay which was not immediately visible to the Approach North controller.

VH-OJG was radar-vectorred by the Approach North controller for a left circuit to runway 16 and this track was observed by the Departures North controller, who decided to issue a reminder about the possible confliction. He decided to call out to the Approach North controller in lieu of using the direct intercom hotline that was available, and although two other controllers heard the call, the Approach North controller did not. VH-OJG was then given a left turn for base leg and during this phase, VH-OJG was turned onto a heading that placed it in conflict with VH-WGG. The approach controller realised the error and immediately attempted to remedy the situation by instructing VH-OJG to maintain 8,500 ft. As the aircraft was already passing 8,600 ft, the inertia was such that the descent was arrested at 7,950 ft before the aircraft was climbed back to the assigned altitude.

The crew of VH-OJG did not see the other aircraft and thought the controller had no urgency in his voice; otherwise they may have been able to arrest the descent earlier than they did when instructed to maintain 8,500 ft.

The pilot of VH-WGG saw VH-OJG as it turned onto the assigned heading and was concerned that the aircraft appeared to be converging. He could see that VH-OJG was turning in front of him at about the same level and queried the altitude with ATC. The departures controller had observed that a separation problem was imminent and gave VH-WGG descent before the pilot's enquiry was answered.

A review of the radar tapes showed that VH-WGG had not commenced descent prior to the point of closest proximity and that the two aircraft came within 1 NM with a vertical difference of 300 ft. The separation standard required is 3 NM or 1,000 ft.

The Approach North controller was experiencing a busy period of arriving air traffic. This involved numerous transmissions to provide a sequencing and separation service for the many aircraft under his control.

2. ANALYSIS

The Approach North controller was in a high-workload situation which required him to concentrate on his section of airspace. VH-OJG was arriving from the east and was being processed through Departures North airspace, which is a normal situation.

The Approach North controller was given the identification and placed the 'shrimp boat' on the radar screen but, in this instance, he forgot about VH-WGG when he vectored VH-OJG onto the base leg. This was partly because the 'shrimp boat' was not positionally updated and the return was not identifiable as an overflying aircraft.

In addition, the pink FPS was not in immediate view, as the approach controllers had decided to put the strip out of the way in order to concentrate on the arrival sequence and to make room for the appropriate arrival FPS.

The Departures North controller was monitoring events as the confliction was developing in his airspace. He expected the approach controller to radar vector VH-OJG clear of VH-WGG but, when he observed the downwind leg of VH-OJG, he decided to remind the approach controller of VH-WGG's presence just in case the other controller had forgotten. The Departures North controller issued the reminder by calling out across the room and did not use the 'hotline' facility that was available between the two positions. The approach controller did not hear the reminder call, and the opportunity to prevent the incident developing was lost.

3. CONCLUSIONS

3.1 Findings

1. ATS staff were correctly rated to perform their tasks.
2. All aircrew performed their functions in accordance with promulgated standards and procedures.
3. The Departures North controller provided the Approach North controller with sufficient information to provide the separation function.
4. The Approach North controller was experiencing a high level of workload.
5. The FPS for VH-WGG was not placed in the correct sequence bay.
6. The Approach North controller did not adequately update his radar display with reference to VH-WGG.
7. The Approach North controller temporarily forgot that VH-WGG was a confliction for VH-OJG.
8. The decision by the Departures North controller to issue a reminder of the confliction was sound practice, but the action was rendered ineffective because he did not use the 'hotline' to pass this reminder.
9. The Approach North controller vectored VH-OJG across the flight path of VH-WGG without ensuring that vertical separation existed.
10. The aircraft passed within 1 NM of each other with 300 ft vertical separation, thereby infringing the standard of 3 NM and 1,000 ft.
11. A breakdown of both vertical and horizontal separation standards occurred.

3.2 Significant Factors

The following factors were considered relevant to the development of the incident:

1. The radar return on the overflying aircraft did not stand out specifically from other aircraft being processed.
2. The Approach North controller did not update his display because of the heavy workload situation.
3. The pink FPS was not in the correct sequence bay and was not immediately visible to the Approach North controller.
4. A warning regarding the developing situation was not heard by the controller.

4. SAFETY ACTIONS

The Bureau of Air Safety Investigation recommends that the Civil Aviation Authority:

1. Allocate special code(s) for overflying aircraft, these codes should be more conspicuous and readily stand out from other radar returns on the radar screen, and
2. Increase the strip holding capacity of the sequence bays in the Sydney approach/departure radar consoles.

CAIR

Confidential Aviation Incident Reporting

Do you...

- have information that you believe is important for aviation safety?
- feel threatened or constrained about revealing this information?

If so...

CAIR is for you. You can submit a CAIR report by using the reporting package distributed in Asia-Pacific AIR SAFETY, sending BASI an ordinary letter or by telephone.

Remember...

- CAIR guarantees to protect your identity
- BASI never seeks to apportion blame or liability
- BASI has no power to take any action which could jeopardise your career
- BASI is concerned ONLY with aviation safety

And...

Your information could result in action to improve aviation safety.

You can contact CAIR at:

PO Box 600
Civic Square ACT 2608
or by telephone on 008-020505

BASI CONTACTS:

Adelaide

GPO Box 1112
Adelaide SA 5001
Telephone: (008)011 034
Facsimile: (08) 228 6808
12th Floor
Capita Building
10-20 Pultney Street
Adelaide SA

Brisbane

PO Box 10024
Brisbane Adelaide St
QLD 4000
Telephone: (008)011 034
Facsimile: (07)832 1386
Australia House
12th Floor
363 Adelaide Street
Brisbane QLD

Canberra (Central Office)

PO Box 967
Civic Square ACT 2608
Telephone: (008) 020 616
Facsimile: (06) 247 3117
24 Mort Street
Braddon ACT

Melbourne

Telephone: (008) 011 034
Facsimile: (03) 685 3611
2nd Floor Building 3
6 Riverside Quay
Southbank Vic. 3006

Perth

PO Box 63
Guildford WA 6055
Telephone: (008) 011 034
Facsimile: (09) 479 1550
Pastoral House
277-279 Great Eastern H'way
Belmont WA

Sydney

PO Box Q78
Queen Victoria Bldg NSW 2000
Telephone: (008) 011 034
Facsimile: (02) 283 1679
7th Floor
1 Market Street
Sydney NSW

CAIR

Reply Paid 22
The Manager
CAIR
PO Box 600
Civic Square ACT 2608
Telephone: (008) 020 505
24 Mort Street
Braddon ACT