

**Aviation Safety Investigation Report
198901528**

**Grumman American Aviation
Corporation AA-1B**

19 January 1989

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198901528 **Occurrence Type:** Accident

Location: Moorooduc Airstrip VIC

Date: 19 January 1989 **Time:** 1030

Highest Injury Level: Serious

Injuries:

| | Fatal | Serious | Minor | None |
|--------------|----------|----------|----------|----------|
| Crew | 0 | 1 | 0 | 0 |
| Ground | 0 | 0 | 0 | - |
| Passenger | 0 | 1 | 0 | 0 |
| Total | 0 | 2 | 0 | 0 |

Aircraft Details: Grumman American
 Aviation Corporation AA-1B

Registration: VH-ERQ

Serial Number: AA1B-0308

Operation Type: Private

Damage Level: Substantial

Departure Point: Moorooduc VIC

Departure Time: N/A

Destination: Moorooduc VIC

Approved for Release: 15th May 1990

Circumstances:

The pilot reported that the engine run up checks were normal, with the engine operating for about ten minutes before the take off was commenced. During take off no anomalies were noted by the pilot, however, at about 100 feet the engine lost nearly all power. The pilot attempted to turn back in order to land on the strip. During the turn, control was lost and the aircraft struck the ground. The area beyond the strip where the power loss occurred was mainly open farmland. The occurrence of a major power loss at low height gave the pilot little time to assess the situation. Inspection of the aircraft did not reveal any mechanical defects which might have caused the engine power loss. The pilot had been using a mixture of Avgas and unleaded motor fuel. This aircraft type was not approved to operate using automotive fuels. Atmospheric conditions were conducive to the formation of significant carburettor ice under all engine power conditions. The use of automotive fuel may have increased the possibility of this occurring. Inspection of the stall warning system revealed that the screws securing the connections to the wing mounted vane assembly were loose, and the system had been inadequately maintained. It was likely that the system was not operating at the time of the accident.

Significant Factors:

The following factors were considered relevant to the development of the accident

1. Conditions conducive to carburettor ice formation.
2. Use of non approved fuel.

3. Engine power loss at a low height.
4. Pilot attempted to turn back to land on the strip from too low an altitude.
5. Poor condition of the stall warning system.
6. Pilot did not ensure adequate airspeed was maintained.