



Australian Government

Australian Transport Safety Bureau

ATSB TRANSPORT SAFETY INVESTIGATION REPORT

Aviation Occurrence Report – 200506294

Final

Engine Failure

74 km SE Melbourne Airport

3 December 2005

de Havilland Canada Dash 8, VH-TQW



Australian Government

Australian Transport Safety Bureau

ATSB TRANSPORT SAFETY INVESTIGATION REPORT

Aviation Occurrence Report

200506294

Final

Engine Failure
74km SE Melbourne Airport
3 December 2005
de Havilland Canada Dash 8, VH-TQW

Published by: Australian Transport Safety Bureau
Postal address: PO Box 967, Civic Square ACT 2608
Office location: 15 Mort Street, Canberra City, Australian Capital Territory
Telephone: 1800 621 372; from overseas + 61 2 6274 6590
Accident and serious incident notification: 1800 011 034 (24 hours)
Facsimile: 02 6274 6474; from overseas + 61 2 6274 6474
E-mail: atsbinfo@atsb.gov.au
Internet: www.atsb.gov.au

© Commonwealth of Australia 2007.

This work is copyright. In the interests of enhancing the value of the information contained in this publication you may copy, download, display, print, reproduce and distribute this material in unaltered form (retaining this notice). However, copyright in the material obtained from non-Commonwealth agencies, private individuals or organisations, belongs to those agencies, individuals or organisations. Where you want to use their material you will need to contact them directly.

Subject to the provisions of the *Copyright Act 1968*, you must not make any other use of the material in this publication unless you have the permission of the Australian Transport Safety Bureau.

Please direct requests for further information or authorisation to:

Commonwealth Copyright Administration, Copyright Law Branch
Attorney-General's Department, Robert Garran Offices, National Circuit, Barton ACT 2600
www.ag.gov.au/cca

ISBN and formal report title: see 'Document retrieval information' on page iii.

DOCUMENT RETRIEVAL INFORMATION

Report No.	Publication date	No. of pages	ISBN
200506294	11 May 2007	5	978-1-921164-74-3

Publication title

Engine Failure, 74km SE Melbourne Airport, 3 December 2005, de Havilland Canada Dash 8, VH-TQW,

Prepared by

Australian Transport Safety Bureau
PO Box 967, Civic Square ACT 2608 Australia
www.atsb.gov.au

Reference No.

May2007/DOTARS 50232

Abstract

At approximately 0725 Eastern Daylight-saving Time on 3 December 2005, during a scheduled passenger service from Wynyard, Tasmania to Melbourne, Victoria, the crew of the de Havilland Canada, Dash 8 aircraft, registered VH-TQW, heard a loud bang from the left side of the aircraft. The crew then observed the loss of the number one (left) engine's torque and oil pressure indication.

Following company procedures, the crew shut down the left engine, advised Melbourne Air Traffic Control of their situation, and continued the approach. A single engine landing was conducted at Melbourne.

A subsequent examination of the aircraft indicated that an internal failure of the left engine had occurred. The engine, a Pratt and Whitney Canada, PW121 model, serial number 120257, was removed from the aircraft and sent to the engine manufacturer's overhaul facility in Singapore for disassembly and examination. The examination was conducted under the supervision of the Air Accident Investigation Bureau of Singapore on behalf of the Australian Transport Safety Bureau (ATSB).

The engine examination found that the engine accessory gearbox bevel gearshaft (towershaft) had failed, separating into three segments. The failed towershaft disrupted the supply of fuel and oil to the engine, resulting in the engine failure.

As a result of this and other, similar, towershaft failures in this engine type, the results of this occurrence and a broader investigation are included in ATSB safety investigation report BO/200501912. That report is available on the ATSB website at : <http://www.atsb.gov.au>.

THE AUSTRALIAN TRANSPORT SAFETY BUREAU

The Australian Transport Safety Bureau (ATSB) is an operationally independent multi-modal Bureau within the Australian Government Department of Transport and Regional Services. ATSB investigations are independent of regulatory, operator or other external bodies.

The ATSB is responsible for investigating accidents and other transport safety matters involving civil aviation, marine and rail operations in Australia that fall within Commonwealth jurisdiction, as well as participating in overseas investigations involving Australian registered aircraft and ships. A primary concern is the safety of commercial transport, with particular regard to fare-paying passenger operations. Accordingly, the ATSB also conducts investigations and studies of the transport system to identify underlying factors and trends that have the potential to adversely affect safety.

The ATSB performs its functions in accordance with the provisions of the *Transport Safety Investigation Act 2003* and, where applicable, relevant international agreements. The object of a safety investigation is to determine the circumstances in order to prevent other similar events. The results of these determinations form the basis for safety action, including recommendations where necessary. As with equivalent overseas organisations, the ATSB has no power to implement its recommendations.

It is not the object of an investigation to determine blame or liability. However, it should be recognised that an investigation report must include factual material of sufficient weight to support the analysis and findings. That material will at times contain information reflecting on the performance of individuals and organisations, and how their actions may have contributed to the outcomes of the matter under investigation. At all times the ATSB endeavours to balance the use of material that could imply adverse comment with the need to properly explain what happened, and why, in a fair and unbiased manner.

Central to the ATSB's investigation of transport safety matters is the early identification of safety issues in the transport environment. While the Bureau issues recommendations to regulatory authorities, industry, or other agencies in order to address safety issues, its preference is for organisations to make safety enhancements during the course of an investigation. The Bureau prefers to report positive safety action in its final reports rather than making formal recommendations. Recommendations may be issued in conjunction with ATSB reports or independently. A safety issue may lead to a number of similar recommendations, each issued to a different agency.

The ATSB does not have the resources to carry out a full cost-benefit analysis of each safety recommendation. The cost of a recommendation must be balanced against its benefits to safety, and transport safety involves the whole community. Such analysis is a matter for the body to which the recommendation is addressed (for example, the relevant regulatory authority in aviation, marine or rail in consultation with the industry).

FACTUAL INFORMATION

At approximately 0725 Eastern Daylight-saving Time¹ on 3 December 2005, during a scheduled passenger service from Wynyard, Tasmania to Melbourne, Victoria, the crew of the de Havilland Canada, Dash 8 aircraft, registered VH-TQW, heard a loud bang from the left side of the aircraft. The crew then observed the loss of the number one (left) engine's torque and oil pressure indication.

Following company procedures, the crew shut down the left engine, advised Melbourne Air Traffic Control of their situation, and continued the approach. A single engine landing was conducted at Melbourne.

A subsequent examination of the aircraft indicated that an internal failure of the left engine had occurred. The engine, a Pratt and Whitney Canada, PW121 model, serial number 120257, was removed from the aircraft and sent to the engine manufacturer's overhaul facility in Singapore for disassembly and examination. The examination was conducted under the supervision of the Air Accident Investigation Bureau of Singapore on behalf of the Australian Transport Safety Bureau (ATSB).

The engine examination found that the engine accessory gearbox bevel gearshaft (towershaft) had failed, separating into three segments. The failed towershaft disrupted the supply of fuel and oil to the engine, resulting in the engine failure.

The towershaft and associated components were sent to the ATSB for technical failure analysis. As a result of this and other, similar, towershaft failures in this engine type, the examination and technical analysis of this failure was incorporated into a broader investigation into towershaft failures on Pratt and Whitney Canada, PW100 series engines.

The results of this occurrence and the broader investigation are included in ATSB aviation safety investigation report BO/200501912. That report is available on the ATSB website at : <http://www.atsb.gov.au>

¹ The 24-hour clock is used in this report to describe the time of day. Eastern Daylight-saving Time was Coordinated Universal Time (UTC) + 11 hours.