COMMONWEALTH OF AUSTRALIA
DEPARTMENT OF CIVIL AVIATION

AIRCRAFT ACCIDENT INVESTIGATION SUMMARY REPORT

Reference No.

AS/692/1052

1. LOCATION OF OCCURREN	CE								
10 miles north west of Scone, New South			Wales		n.s.l. (ft) feet	Dote 22.10.69	Time (Local) 1530		EST
2. THE AIRCRAFT									
Moke and Model		Registration		Certificate of Airworthiness		Valid from		alid to	
Cessna 180C		VH-BBN				2.2.65	1	1.2.74	
Registered Owner Pay and Williamson Pty. Ltd.,		Pay and Williamson Pty. Ltd.,			Ltd	Degree of damage to aircraft Destroyed			
P.O. Box 158,		P.O. Box 158,			Lita.,	Other property damaged			
Scone, N.S.W.		1	N.S.W.			Nil			
Defects discovered		beone,	11.0, 11.						
	•								
		•			. •				
						•			•
							<i>x</i> .		
3. THE FLIGHT					 				
Last or intended departure point	Time of departure	Next point of intended landing Purpose of f			ight Class of operation				
gricultural Strip	1515	Point	t of depart	ure Superpho		ARTIAL WOLK			
					Spread	ing			
4. THE CREW	· · · · · · · · · · · · · · · · · · ·								
Name	Status	Age	Class of	licence	Hours on type	Total hours	Degree of injury		
Robert Graham									
MINSHALL	Pilot	25 Comm		nercial 470		653	. F	Fatal	
		<u> </u>			<u> </u>	<u> </u>	<u> </u>		
5. OTHER PERSONS (All pass	engers and persor	s injured o	n ground)						
Name	Status	Degree of	injury .	Nome		Status		Degree	of injur
							.	ı	
<u> </u>								<u> </u>	
6. CONTRAVENTIONS OF RE	GULATIONS AND	ORDERS							
Regulation or Order No.				Nature of c	contravention			·	:
į									
					•				
7. RELEVANT EVENTS									

The aircraft was engaged in superphosphate spreading in hilly country and, after commencing operations at approximately 1400 hours, had completed seven sorties. The runs were made in predominantly easterly and westerly directions and the eastern end was close to the main north-south ridge of the Brawboy Range. The aircraft had been observed turning at the eastern end of the runs by proceeding out through gaps in the ridge and then returning across the crest of the range to spread in a westerly direction. At the termination of the last completed run to the east the aircraft was seen to pull up high and turn inside the face of the ridge before descending and disappearing from the view of the witness. Smoke was seen to rise from the area immediately and the burning wreckage was sighted shortly afterwards by searching aircraft.

8. OPINION AS TO CAUSE

It is probable that the pilot lost control of the aircraft during a turn and recovery could not be effected in the height available. It has not been possible from the evidence available to determine the reason for loss of control.

Papert approved	
. abeli abbioseo	
	1 1/2
	Make

.(D.S. GRAHAM)

Assistant Director-General (Air Safety Investigation) Date 11.11.1970