COMMONWEALTH OF AUSTRALIA DEPARTMENT OF CIVIL AVIATION

LOCATION OF OCCURRENCE

## AIRCRAFT ACCIDENT INVESTIGATION SUMMARY REPORT

Reference No.

AS/703/1010

				Height a.		Date Time (Lo		)	Zone EST
Paynesville, Victoria				10 fe	et	24.1.70   1545			ro1
2. THE AIRCRAFT	·					Valid from			
Make and Model Piper PA28-140 "Cheroke	Registration VH-RSS			Certificate of Airworthiness			Valid to 25.6.76		
Registered Owner	Operator				Degree of damage to aircraft				
Royal Aero Club of New So	1 -			outh Wales,					
P.O. Box 255,		Sox 255,			Other property damaged				
Bankstown, N.S.W.	Banksto	own, N.	S.W.	V		Nil			
Defects discovered									
·									•
3. THE FLIGHT							<u> </u>	<del></del>	
Last or intended departure point Time of departure Next point of intend					led landing Purpose of flight Class of operation				
Merimbula	1345	I	nesvill	-	Travel		Private		
THE CREW	<u> </u>								
Name	Status	Age	ge Class of lice		Hours on type	Total hours	Deg	Degree of injury	
Edward William									
O'SULLIVAN	Pilot	57	Pr	rivate	116	382	Nil		
		<u> </u>	·			<u> </u>	<u> </u>		
5. OTHER PERSONS (All passengers and persons injured on ground)									
Nome	Status	Degree of injury			Nome	5	tatus	Degree	of injury
W. SHELLEY	Passenger	Nil	Nil				·		
B REYNOLDS	Passenger	Nil							
6. CONTRAVENTIONS OF RE	GUI ATIONS AND	ORDERS						<del></del>	
6. CONTRAVENTIONS OF REGULATIONS AND ORDERS  Regulation or Order No. Nature of contravention									
ļ.				*				•	
					<del></del>				
7. RELEVANT EVENTS	<del></del>					·····			
After an uneventful flight f	rom Marimbul	a tha nile	ot overf	low the str	in at Dayna	cville and r	node a air	ouit	
prior to landing into the ea		_			-				1
hand brake and about this		-							
centre of the rudder toe-b		_				•			
endeavoured to free his fo	-				_	-		e but	
the aircraft veered in a ge		_		-					e e
post against which the airc	eraft came to r	est.							
	•								
									•
0 0000000000000000000000000000000000000			<del></del>				· · · · · · · · · · · · · · · · · · ·		
8. OPINION AS TO CAUSE									

The cause of the accident was that the pilot was distracted from maintaining directional control when

(D.S. GRAHAM)

Assistant Director-General (Air Safety Investigation)

11.11.1970

CA 149

Pepart approved

his foot became jammed in the rudder pedal.