



GOVERNMENT OF AUSTRALIA

DEPARTMENT OF TRANSPORT

AIRCRAFT ACCIDENT INVESTIGATION SUMMARY REPORT

Reference No.

AS/742/1055

Publication of this report is authorised by the Secretary under the provisions of Air Navigation Regulations 283 (1)

1. LOCATION OF OCCURRENCE

Near Coffs Harbour Aerodrome, New South Wales	Height a.m.s.l. 10 feet	Date 23.10.74	Time (Local) 1244 hours	Zone EST
---	----------------------------	------------------	----------------------------	-------------

2. THE AIRCRAFT

Make and Model Beech A23/24	Registration VH-DDA	Certificate of Airworthiness Valid from 19.9.67 to 18.9.76
Certificate of Registration issued to J. L. Langan Pty. Ltd., 59 Tuffy Avenue, Sans Souci, N.S.W.	Operator J. L. Langan, 59 Tuffy Avenue, Sans Souci, N.S.W.	Degree of damage to aircraft Destroyed
		Other property damaged Nil
Defects discovered		

3. THE FLIGHT

Last or intended departure point Coffs Harbour	Time of departure 1242 hours	Next point of intended landing Bankstown	Purpose of flight Travel	Class of operation Private
---	---------------------------------	---	-----------------------------	-------------------------------

4. THE CREW

Name	Status	Age	Class of licence	Hours on type	Total hours	Degree of injury
John Leslie LANGAN	Pilot	62	Private	300	1500	Serious

5. OTHER PERSONS (All passengers and persons injured on ground)

Name	Status	Degree of injury	Name	Status	Degree of injury

6. RELEVANT EVENTS

The aircraft took off from Runway 10 at Coffs Harbour and commenced to climb in an easterly direction. At an altitude of about 300 feet, there was an abnormal engine noise and the pilot commenced a left hand turn with the intention of returning for a landing. Very shortly after the turn was commenced a substantial reduction of engine power occurred and, in preparation for a forced landing, the pilot discontinued the turn and headed towards what he believed to be a clear area. The pilot raised the nose of the aircraft as it descended and eventually crashed into trees situated some 400 metres east-north-east of the upwind end of the runway from which it departed.

A detailed examination of the aircraft wreckage, including the engine, was carried out. It was found that all the main engine bearing shells exhibited evidence of fretting on the outer surfaces as a result of micro-movement within the crankcase halves and, at some considerable operating time prior to the accident, bearing metal pick-up had occurred in the rear half of the front main bearing. It is unlikely that the condition of the bearings would have resulted in any significant resistance to engine rotation.

7. OPINION AS TO CAUSE

The cause of the accident was a substantial loss of engine power in a position from which a successful forced landing was unlikely. The reason for the loss of engine power has not been determined.

Approved for
publication(I. M. Leslie)
Delegate of the SecretaryDate
16.12.1976