1

Aviation Safety Investigation Report 199100039

Britaero 146 - 300 Airbus A300 - B4-600

13 July 1991

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199100039 Occurrence Type: Incident

Location: Sydney NSW

Date: 13 July 1991 **Time:** 935

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	0

Aircraft Details: Britaero 146 - 300 Airbus A300 - B4-600

Registration: VH-EWS VH-YMK

Serial Number: E3197 556

Operation Type: Regular Public Transport Regular Public Transport

Damage Level: Nil Nil

Departure Point: Sydney NSW Sydney NSW

Departure Time: N/A

Destination: Hamilton Island QLD Perth WA

Approved for Release: 16th October 1991

Circumstances:

VH-EWS was departing from runway 16 at Sydney for Hamilton Island, followed shortly after by VH-YMK for Perth. The DEPARTURE Radar Controllers on duty at the Sydney Area Approach Control Centre (AACC), believed that a breakdown in the radar separation standard had occurred between the two aircraft shortly after take-off. The initial DEPARTURE instructions given to the Sydney Control Tower for VH-YMK were 'Cancel SID turn right heading 170 maintain 3 000'. The DEPARTURE sequence was subsequently changed twice with two aircraft VH-HVA and VH-EWS sequenced ahead of VH-YMK. Immediately following the issue of the final DEPARTURE instruction for VH-EWS, the instruction 'and YMK can be unrestricted' was passed by DEPARTUREs to the Tower. The Tower understood the instruction to mean cancel the previous DEPARTURE instruction, and the aircraft may now track via the cleared SID with no altitude restriction. The

Significant Factors:

The following factors were considered relevent to the development of the incident:

- 1. There was a breakdown in co-ordination between the Departures and Tower Controllers.
- 2. There was a different expectation and understanding of the departure instruction between the Departures and Tower Controllers.