

**Aviation Safety Investigation Report
198702436**

Beechcraft 95-B55 Baron

9 November 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198702436
Location: Brewarrina NSW
Date: 9 November 1987
Highest Injury Level: Nil
Injuries:

Occurrence Type: Accident

Time: 1527 ESuT

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Beechcraft 95-B55 Baron
Registration: VH-EHN
Serial Number: TC-1285
Operation Type: Charter (Cargo Operations)
Damage Level: Substantial
Departure Point: Brewarrina NSW
Departure Time: N/A
Destination: Bourke NSW

Approved for Release: 16 March 1988

Circumstances:

The pilot reported that as full power was applied on the take-off run, he heard a loud bang and the aircraft yawed to the right. He shut down the right engine and brought the aircraft to a stop. Initial inspection revealed that the right propeller assembly had failed at the hub. One blade had separated from the hub and struck the nose section of the aircraft. It was determined that the hub had failed from fatigue which had originated at the root of the blade retention thread. It was estimated that the fatigue crack had propagated over about 900 engine start cycles, and had occurred at some time after a regular inspection to check for this type of cracking.