1

Aviation Safety Investigation Report 198702452

Petzetel SZD41A Jantar

30 December 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198702452 Occurrence Type: Accident

Location: 10 km East of Lockhart NSW

Date: 30 December 1987 **Time:** 1510 ESuT approx

Highest Injury Level: Fatal

Injuries:

	Fatal	Serious	Minor	None
Crew	1	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	1	0	0	0

Aircraft Details: Petzetel SZD41A Jantar

Registration: VH-WQX
Serial Number: B721
Operation Type: Private
Damage Level: Destroyed
Departure Point: Corowa NSW

Departure Time: 1245

Destination: Corowa NSW

Approved for Release: 22 March 1988

Circumstances:

The pilot was participating in a 500 kilometres cross country gliding competition. Atmospheric conditions were not favourable for prolonged soaring flight, and none of the other participants was able to cover any significant distance. However, this particular aircraft departed on the planned track, and the next reported sighting was about 3 kilometres from the accident site. At this time the aircraft was circling at approximately 300 feet above the ground and tracking to the north-west. No further sightings were reported, and the wreckage of the aircraft was subsequently discovered in a paddock 102 kilometres from the DEPARTURE aerodrome, on the intended track. Investigation revealed that the glider had initially contacted the ground with the leading edge of the right wing, while the aircraft was in a steep nose-down attitude and spinning to the right. There were no known witnesses to the accident, and it could not be established whether the pilot had been attempting to outland or to find a thermal at low level. There was no evidence of any pre-existing mechanical defect which might have contributed to this occurrence. It was probable that control of the glider was lost during a manoeuvre at low speed and height above the ground, however the reason for the loss of control was not determined.