Aviation Safety Investigation Report 198600693

Bellanca Scout 8GCBC

23 March 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198600693 Occurrence Type: Accident

Location: Harts Range NT

Date: 23 March 1986 **Time:** 849

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	2
Total	0	0	0	3

Aircraft Details: Bellanca Scout 8GCBC

Registration: VH-PEV

Serial Number:

Operation Type: Private-Business **Damage Level:** Substantial

Departure Point: Bond Springs NT

Departure Time: 0849

Destination: Harts Range NT

Approved for Release: May 5th 1986

Circumstances:

During the landing roll both mainwheels entered soft areas in the strip surface. The aircraft swung through 120 degrees to the left then slid sideways for 17 metres before the right maingear collapsed. The wing struck the ground and was bent upwards. The condition of the strip surface was unsatisfactory because the first 500 metres contained soft spots. The positions of the soft spots were not marked, nor was the strip threshold displaced. The pilot had used the strip previously but on this occasion he did not check its serviceability before the flight.