

Aviation Safety Investigation Report
198702459

Maxair Drifter XP503

31 May 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198702459

Location: Taylors Arm NSW

Date: 31 May 1987

Highest Injury Level: Serious

Injuries:

Occurrence Type: Accident

Time: 1650 approx

	Fatal	Serious	Minor	None
Crew	0	1	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	1	0	0

Aircraft Details: Maxair Drifter XP503

Registration: Not Registered

Serial Number:

Operation Type: Miscellaneous (Sport
Aviation)

Damage Level: Substantial

Departure Point: Taylors Arm NSW

Departure Time: 1650 approx

Destination: Taylors Arm NSW

Approved for Release: November 20th 1987

Circumstances:

The aircraft had completed several successful flights during the day. At the completion of a power off descent, the pilot rapidly opened the throttle. The engine began running roughly and then failed completely. During the subsequent glide approach, for a forced landing, the aircraft collided with powerlines which crossed a gully about 350 feet above the ground. One line contacted the pilot's throat, inflicting severe lacerations, and the aircraft descended to the ground out of control. An inspection of the engine did not reveal any defects that could have contributed to the occurrence. This particular type of engine, which has inverted cylinders, floods quickly with rapid advance of the throttle. This flooding with unburnt fuel, swamps the spark plugs causing the engine to fail.