## 1

**Aviation Safety Investigation Report 198602659** 

**Grob Twin Astir 102** 

27 July 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602659 Occurrence Type: Accident

**Location:** Elliott River, 28km SW of Bundaberg QLD **Date:** 27 July 1986 **Time:** 1100

**Highest Injury Level:** Serious

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	1	0	0
Ground	0	0	0	-
Passenger	0	0	0	1
Total	0	1	0	1

**Aircraft Details:** Grob Twin Astir 102

**Registration:** VH-IKV

**Serial Number:** 

**Operation Type:** Private (Gliding) **Damage Level:** Substantial

**Departure Point:** Elliott River QLD

**Departure Time:** N/A

**Destination:** Elliott River QLD

**Approved for Release:** May 1st 1987

## **Circumstances:**

The glider was being winch launched. The launch was normal until the glider reached an altitude of about 70 feet above the strip when the winch cable went slack. The aircraft was levelled before commencing a descent and the landing flare was initiated at about 10 feet above the strip. The aircraft then stalled, landed heavily and bounced. The wheel collapsed during the landing roll. The winch engine failed during the launch due to an ignition problem.