

Aviation Safety Investigation Report 198701446

Airbus A300-B4-203

18 October 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198701446 Occurrence Type: Accident

Location: Melbourne VIC

Date: 18 October 1987 **Time:** 1315

Highest Injury Level: Serious

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	8	8
Ground	0	0	0	-
Passenger	0	2	62	173
Total	0	2	69	181

Aircraft Details: Airbus A300-B4-203

Registration: VH-TAC

Serial Number: 157

Operation Type: Regular Public Transport

Damage Level: Minor

Departure Point: Sydney NSW

Departure Time: 1215

Destination: Melbourne VIC

Approved for Release: 3 May 1988

Circumstances:

As the aircraft was nearing the end of the landing roll, the Tower Controller observed smoke briefly issuing from one of the wheel assemblies. The crew was alerted, and reported that a hot brake temperature warning was indicated on the flight deck. The smoke had not persisted, and the pilot in command elected to continue taxying to the terminal area, in order to allow a normal disembarkation of the passengers. He requested the Tower to monitor the situation. The Airport fire services were summoned and followed the aircraft. Another Tower Controller then reported that fire had broken out in the left maingear. The aircraft was halted and the pilot in command ordered an evacuation. The evacuation proceeded smoothly, but injuries resulted from the use of the escape slides. The fire crews rapidly extinguished the fire and assisted with the evacuation process. Investigation revealed that an electrical short circuit had occurred in a solenoid in the anti-skid system which controls the brakes on one of the left mainwheels. This led to the brakes on the affected wheel being applied continuously. The resulting overheating in turn led to the eventual disintegration of the brake disc and pads, and the outer covering of an hydraulic line caught fire. Considerable overheating of the tyre and wheel rim also took place. The crew had no direct communication with the fire crews on site, and were unaware of the extent of the fire. This had left the pilot in command with no alternative but to order the evacuation of the aircraft.