1

Aviation Safety Investigation Report 198503521

Piper PA28-151

14 July 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198503521 Occurrence Type: Accident

Location: Redcliffe QLD

Date: 14 July 1985 **Time:** 1650

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	1	2
Total	0	0	1	3

Aircraft Details: Piper PA28-151 **Registration:** VH-PZW

Serial Number:

Operation Type: Private-practice
Damage Level: Substantial
Departure Point: Redcliffe QLD

Departure Time: 1650

Destination: Redcliffe QLD

Approved for Release: March 20th 1986

Circumstances:

After completing the first landing of the intended touch and go, the pilot readjusted the elevator trim, flap, and applied full power. As the speed increased to about 65 knots he attempted to select the climb attitude but found that the elevator control was jammed in the neutral position. The take-off was abandoned. However, the pilot was unable to stop the aircraft before it overran the strip and struck a levee bank. An inspection of the aircraft revealed that a small aerosol container had jammed the elevator control cables. Sometime prior to this flight the aerosol container had been left lying loose in the rear luggage compartment. It had rolled between the alloy mesh screen and the lower rear seat back into an area under the rear seat where it could foul control cables. When the take-off was abandoned very little braking was available, in the initial stages, because the aircraft was wheelbarrowing due to its speed and the jammed elevator.