

**Aviation Safety Investigation Report  
199003137**

**Moyes GTR 162**

**27 October 1990**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199003137

**Occurrence Type:** Accident

**Location:** O'Reilly's Mountain (35 km W Brisbane) QLD

**Date:** 27 October 1990

**Time:** 1515

**Highest Injury Level:** Fatal

**Injuries:**

	Fatal	Serious	Minor	None
Crew	1	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
<b>Total</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>0</b>

**Aircraft Details:** Moyes GTR 162

**Registration:** N/A

**Serial Number:** N/A

**Operation Type:** Private

**Damage Level:** Substantial

**Departure Point:** O'Reilly's Mountain

**Departure Time:** N/A

**Destination:** Samford Valley QLD

**Approved for Release:** 26th February 1991

#### **Circumstances:**

The pilot had not flown for about three weeks and was conducting his first Hang gliding flight from the site. The site was advanced rated and the wind conditions were light and variable with occasional thermal gusts. The pilot was assisted in setting up the glider but declined launch assistance. He appeared anxious to begin the flight and was not seen to perform the mandatory hang check to confirm his attachment to the glider. Following a good launch the glider was observed to sink rapidly and fly in a straight path towards a large tree some 30 metres in front of the launch site. The glider struck the tree trunk and the pilot was thrown clear. Examination of the equipment revealed no damage to the harness support system and no other pre-existing fault or damage. The flight path observed was typical of what would be expected if the pilot had failed to connect his harness to the glider.

#### **Significant Factors:**

The following factors were considered relevant to the development of the accident

1. The pilot apparently failed to perform a hang check before launch.
2. In not being attached to the glider the pilot was denied the normal means of control during flight.
3. The pilot was unable to avoid the obstruction.