

**Aviation Safety Investigation Report
199001958**

Cessna 182-P

2 January 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199001958 **Occurrence Type:** Accident
Location: "Roeta Station" 60 km west of Hillston NSW
Date: 2 January 1990 **Time:** 1200
Highest Injury Level: Nil
Injuries:

| | Fatal | Serious | Minor | None |
|--------------|----------|----------|----------|----------|
| Crew | 0 | 0 | 1 | 1 |
| Ground | 0 | 0 | 0 | - |
| Passenger | 0 | 0 | 0 | 3 |
| Total | 0 | 0 | 0 | 4 |

Aircraft Details: Cessna 182-P
Registration: VH-WLX
Serial Number: 18264780
Operation Type: Private
Damage Level: Substantial
Departure Point: "Roeta Station" NSW
Departure Time: N/A
Destination: Maitland NSW

Approved for Release: 15th February 1990

Circumstances:

The owner pilot carried out a pre-flight check of the aircraft, which included a check of the fuel for contamination. The aircraft had last been refuelled at Maitland, prior to the flight to "Roeta". The weather was reported as fine and clear, with a temperature of about 35 degrees celsius. The wind was from the southwest at about 5 knots. The gravel strip was level and estimated to be about 3000 feet in length. The pilot said he used the strip on numerous occasions over the past 10 years in this, and other aircraft. Take-off was conducted into wind, using the full length of the strip. Although engine power indications and acceleration appeared normal, the pilot said he was aware that the aircraft appeared to require a greater distance to reach take-off speed. He attributed this to the outside air temperature. At an indicated airspeed of 60 knots, with inadequate strip length remaining to safely abort the take-off, the aircraft was flown off the ground. This was followed by an immediate and complete loss of engine power. Maximum flap was extended and the aircraft landed on the strip remaining. The aircraft continued beyond the strip end, across a road and associated table drain, before coming to rest. Although the reason for the loss of power was not established, water contamination of the fuel is considered by the pilot to be a strong possibility. The aircraft is fitted with bladder type fuel cells which can harbour water not easily detectable. The aircraft had had little use over the previous three months, during which time it had been parked in the open on level surfaces. On the two days prior to the accident the aircraft had been parked on a slope. It is considered by the pilot that water could have migrated from low points in the fuel cells to a position where it may have been ingested by the engine, resulting in a sudden loss of power.