Aviation Safety Investigation Report 198602656

Cessna 172 F

4 July 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602656 Occurrence Type: Accident

Location: Yaralla Station QLD, 80 km NW Goodooga NSW **Date:** 4 July 1986 **Time:** 1115(Aprx)

Highest Injury Level: Fatal

Injuries:

| | Fatal | Serious | Minor | None |
|-----------|-------|---------|-------|------|
| Crew | 2 | 0 | 0 | 0 |
| Ground | 0 | 0 | 0 | - |
| Passenger | 0 | 0 | 0 | 0 |
| Total | 2 | 0 | 0 | 0 |

Aircraft Details: Cessna 172 F **Registration:** VH-DNU

Serial Number:

Aerial Work-Dual

Operation Type: Activation Instruction

Damage Level: Destroyed

Departure Point: Yaralla Station QLD

Departure Time: 1115(Aprx)

Destination: Yaralla Station QLD

Approved for Release: March 18th 1987

Circumstances:

The pilot in command was continuing a mustering endorsement which had been commenced the previous day. After flying for about 85 minutes the pilots stopped for a break of some 30 minutes. About 75 minutes after flying had recommenced a person on the ground heard a thump, and the wreckage of the aircraft was discovered shortly afterwards. It had struck the ground in a steep nose down attitude while spinning or turning to the left, about 270 metres to the south of the 30 strip. Investigation revealed that, at some stage prior to the final impact with the ground, the undersurface of the left wing had contacted the ground, causing left aileron failure followed by a loss of controllability. Medical evidence indicated that the pilot may have suffered a partial or complete loss of consciousness due to a pre-existing heart condition. However, it could not be determined whether this was a factor in the accident.