

**Aviation Safety Investigation Report
199000589**

Piper PA-23

19 June 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199000589
Location: Port Hurd NT
Date: 19 June 1990
Highest Injury Level: Nil
Injuries:

Occurrence Type: Accident

Time: 930

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Piper PA-23
Registration: VH-DCQ
Serial Number: 27-7954012
Operation Type: Charter
Damage Level: Substantial
Departure Point: Pickertaramoor NT
Departure Time: 0916
Destination: Port Hurd NT

Approved for Release: 13th September 1990

Circumstances:

The pilot reported that he was positioning for a pickup of passengers and he had completed a visual circuit and approach to the strip. He achieved a gentle touchdown within 100 metres of the threshold of the 1065 metre strip on both main wheels. Coincident with lowering the nosewheel onto the strip, the pilot reported feeling the aircraft lurch which he first took to be symptomatic of a flat tyre on the left maingear. He had no trouble maintaining directional control. A little later, the left wing dropped further and the gear warning horn sounded. The pilot was able to keep the aircraft within the defined width of the strip and, on coming to rest, he shut down the aircraft before egressing. A post flight inspection by the pilot showed that the left maingear oleo leg had swung rearwards and the lower surface of the flaps had been dented by the tyre. The reduced ground clearance had allowed the left propeller to strike the ground but the left maingear doors were out of contact with the ground. A detailed inspection of the maingear components showed that the left maingear drag link centre bolt had failed in fatigue. Furthermore, all the landing gear components showed signs of wear beyond tolerances and this condition was evident of inadequate maintenance and inspection.

Significant Factors:

The following factors were considered relevant to the development of the accident

1. Fatigue failure of the left maingear drag link centre bolt.
2. Probable inadequate maintenance and inspection. This accident was not the subject of an on-scene investigation.