

**Aviation Safety Investigation Report  
199000032**

**Cessna 172L**

**23 December 1990**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199000032  
**Location:** Mittagong NSW  
**Date:** 23 December 1990  
**Highest Injury Level:** Serious  
**Injuries:**

**Occurrence Type:** Accident

**Time:** 1050

	Fatal	Serious	Minor	None
Crew	0	1	0	0
Ground	0	0	0	-
Passenger	0	3	0	0
<b>Total</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>

**Aircraft Details:** Cessna 172L  
**Registration:** VH-SUK  
**Serial Number:** 17259926  
**Operation Type:** Private  
**Damage Level:** Substantial  
**Departure Point:** Mittagong NSW  
**Departure Time:** 1045  
**Destination:** Mittagong NSW

**Approved for Release:** 10th July 1991

#### **Circumstances:**

The aircraft was loaded close to its maximum all-up weight and departed from runway 24. The takeoff was normal and the aircraft was airborne within 500 metres. After takeoff, a right turn was commenced which is normal procedure to avoid the rising terrain. The aircraft was apparently performing normally and climbing at about 65 to 70 knots. However, approaching a row of pine trees, it began to lose height. Despite the pilot maintaining the aircraft in the climb attitude, and using full engine power, the aircraft continued to lose height until ground impact. Although fire rapidly developed after impact the pilot successfully assisted the passengers to evacuate. No pre-accident defects were found with the aircraft which could have contributed to the accident. At the time of the accident, a low pressure of 995 hPa was situated over the area. This combined with the surface temperature of about 28 to 30 degrees Celsius to produce a density altitude of 4650 feet at the airfield which is 1850 feet above sea level. The weather pattern was also producing gusty winds and mechanical turbulence over the surrounding hills. A combination of high density altitude and high aircraft all-up weight resulted in a best achievable rate of climb of about 400 feet per minute. This was reduced by the effects of downdrafts, turbulence and the turn, with the result that the aircraft could not outclimb the terrain.

#### **Significant Factors:**

The following factors were considered relevant to the development of the accident

1. High density altitude.
2. High aircraft all-up weight.
3. Turbulence and downdrafts over the surrounding hills.

4. Pilot's low aeronautical experience level.