Aviation Safety Investigation Report 198300067

Bell 47G-5A

24 October 1983

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

| Occurrence Number: Location: Date: Highest Injury Level: Injuries: | | 29 km NNE of Wando Vale QLD 24 October 1983 | | | Occurrence Type: Accident Time: 735 | |
|---|-------------------------------|--|----------------------|------------------------|--|---------------------|
| U | | Crew Ground Passenger | Fatal 0 0 0 | Serious 0 0 0 | Minor 1 0 0 | None 1 - 1 |
| Aircraft Details: Registration: | | | | | | 2 |
| Serial Number: Operation Type: Damage Level: Departure Point: Departure Time: Destination: | Substantial Wando Vale QLD | | | | | |

Approved for Release: 28th February 1984

Circumstances:

The pilot elected to conduct a practice autorotation. His initial intention was to reapply power and to discontinue the exercise before reaching the ground, but during the descent he changed his mind and decided to continue to the ground. As the pilot flared the helicopter the tail skid contacted the ground and the main rotors struck the tail boom and tail rotor shaft. The pilot chose an unfamiliar sand bar on which to practice the autorotational landing. The associated glare from such a surface and the lack of visual cues for height assessment are considered to have led the pilot to misjudge his height for the flare.