Aviation Safety Investigation Report 198401372

Bell 47-G4

24 March 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		"Burwood", 23 km W of Werris Cr 24 March 1984				e Type: Accident
			Fatal	Serious	Minor	None
		Crew	0	1	0	0
		Ground	0	0	0	-
		Passenger	0	0	0	0
		Total	0	1	0	0
Aircraft Details: Registration: Serial Number: Operation Type: Damage Level: Departure Point: Departure Time: Destination:	VH-UT Aerial S Destroy "Burwo 0	Q Spraying red	-			

Approved for Release: 9th August, 1984

Circumstances:

The pilot was inspecting areas of noxious weeds to check on the results of recent spraying. The helicopter struck a power line which severed the bubble windscreen. The wire then contacted the pilot's throat before being cut by the main rotor. The helicopter struck the ground tail rotor first about 35 metres beyond the point of collision. After extricating himself from the wreckage, the pilot swam across a river, walked 3 kilometres to a homestead and drove 15 kilometres for help. He was later admitted to intensive care in hospital. The pilot had been informed that there were power lines in the area, but was unaware of their precise location. He had conducted a survey flight prior to commencing the spraying operation, but had not sighted the particular cables. There was evidence to indicate that the helicopter had flown under the cables on at least one occasion while spraying. The cables, which spanned a river, were supported by poles which were 253 metres apart and which were probably outside the pilot's normal field of vision.