

Aviation Safety Investigation Report 199001992

Beech A36

11 June 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199001992 **Occurrence Type:** Accident
Location: 1.6 km south-east of Medowie NSW
Date: 11 June 1990 **Time:** 434
Highest Injury Level: Nil
Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	4
Total	0	0	0	5

Aircraft Details: Beech A36
Registration: VH-MAO
Serial Number: E-1226
Operation Type: Private
Damage Level: Substantial
Departure Point: Coolangatta Qld
Departure Time: 0229
Destination: Bankstown NSW

Approved for Release: 15th May 1991

Circumstances:

During preflight inspection the pilot visually checked that both fuel tanks were full. About two hours after DEPARTURE, whilst cruising at 7000 feet, the engine suffered a sudden and total loss of power. The pilot immediately selected the left fuel tank but was unable to restore power. As both fuel contents gauges were indicating above half, the pilot reselected the right fuel tank and unsuccessfully continued attempts to restart the engine. The aircraft was force-landed in a swamp, coming to rest intact, but partially submerged. The occupants were able to escape onto the right wing and were rescued by helicopter a short time later. Investigation revealed the right fuel tank cap was unfastened and the tank contained only one litre of fuel. Although the left tank cap was partially unlocked, the tank opening was sealed. That tank contained about 65 litres of fuel. The locking mechanism on both tank caps was extremely stiff and difficult to operate. The unfastened right fuel tank cap had allowed most of the fuel to vent from the tank opening during flight. The engine, which was operating from the right tank, lost power when all fuel was exhausted from the tank. The venting action also caused the bottom of the fuel cell to rise, biasing the fuel contents gauge to indicate about half full. It is believed the engine did not restart with the left tank selected because the pilot did not allow sufficient time for air to be purged from the engine fuel injection system.

Significant Factors:

It is considered that the following factors were relevant to the development of the accident

1. Both fuel tank caps were extremely difficult to lock closed.
2. The preflight inspection was inadequate and both fuel caps were not correctly locked before flight.
3. Fuel was lost from the right tank in flight.

4. The right fuel gauge incorrectly indicated the quantity of fuel in the right tank.
5. The engine lost power due to fuel starvation.