

**Aviation Safety Investigation Report  
198702392**

**Bell 47-G2**

**10 March 1987**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

This accident was not subject to an on scene investigation.

**Occurrence Number:** 198702392      **Occurrence Type:** Accident  
**Location:** Torry Plains Station (90 km NE Balranald) NSW  
**Date:** 10 March 1987      **Time:** 1230  
**Highest Injury Level:** Nil  
**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
<b>Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>1</b>

**Aircraft Details:** Bell 47-G2  
**Registration:** VH-KHK  
**Serial Number:**  
**Operation Type:** Private (Property Inspection)  
**Damage Level:** Substantial  
**Departure Point:** Torry Plains Station NSW  
**Departure Time:** 1230  
**Destination:** Torry Plains Station NSW

**Approved for Release:** July 8th 1987

**Circumstances:**

The pilot reported that as he brought the aircraft into the hover in preparation for landing, it sank to the ground from a height of about 15 feet. The tailrotor blades struck a lygnum bush and the drive shaft sheared. The pilot indicated that the main rotor rpm had decayed, possibly from over-pitching during the latter stages of the approach. Operations had been conducted in gusty wind conditions. When the pilot noted that the main rotor speed had decayed to 2800 rpm, he applied more power but was unable to arrest the rate of descent.