

Aviation Safety Investigation Report
199102554

Beech C23

22 September 1991

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199102554 **Occurrence Type:** Accident
Location: Manning Stn (40 km SSE Tambo) Qld
Date: 22 September 1991 **Time:** 0735 hours
Highest Injury Level: Fatal
Injuries:

	Fatal	Serious	Minor	None
Crew	1	0	0	0
Ground	0	0	0	-
Passenger	1	0	0	0
Total	2	0	0	0

Aircraft Details: Beech C23
Registration: VH-WHP
Serial Number: M-1544
Operation Type: Aerial work
Damage Level: Destroyed
Departure Point: Manning Stn Qld
Departure Time: 0730 hours
Destination: Manning Stn Qld

Approved for Release: 24th August 1992

Circumstances:

The pilot was to conduct seeding operations on a friend's property. On arrival at the strip, he removed the front right seat from the cabin, leaving only the pilot's seat in the aircraft (the rear passenger seats were not in the aircraft). The pilot then fitted shaped metal sheets to the top and bottom of the baggage door. The door was positioned at the rear of the cabin on the left side of the aircraft. The metal sheets enabled the door to be held open (at an angle of about 17°) during flight, to allow seed to be dispensed through the opening. The seed mixture was contained in bags, each weighing about 45 kg. Four bags were loaded into the aircraft cabin. One bag was placed adjacent to the baggage door. The person dispensing the seed then sat on the cabin floor leaning against the cabin rear bulkhead. Two further bags were placed on the floor in the area normally occupied by the rear passenger seats and another bag on the floor in the position of the front right seat. About 10 min after the aircraft departed for the seeding area, the property owner became concerned that he had not seen or heard the aircraft and commenced a search. He located the wreckage some 25 min later. From the evidence available at the site, the aircraft impacted the ground at low speed and with a high rate of descent. Some flap (probably one notch on the selection handle) was selected at impact but whether this was a normal configuration for seeding operations could not be determined. The impact was not survivable, the forces being sufficient to cause the pilot's inboard lap safety belt attachment bracket to fail in overload. Examination of the seed bags indicated that one bag was probably empty of seed at impact. Nothing to indicate a pre-existing defect in the aircraft controls or engine was found. It appears that the pilot had conducted one seeding run and was conducting a right procedure turn to position for the next run when the accident occurred. It was established that the pilot had received no formal training in low flying or aerial agriculture techniques. The exact sequence of events leading to this accident could not be determined.