

**Aviation Safety Investigation Report
198800011**

Boeing 747-238SP

14 May 1988

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

currents associated with an isolated towering cumulus cloud, which evidently contained insufficient moisture to be detectable by weather radar.

Significant Factors:

It was considered that the following factors were relevant to the development of the incident:

1. The ability of the flight crew to visually detect significant cloud formation was substantially affected by dark, moonless conditions.
2. The cloud formation encountered by the aircraft lacked sufficient moisture to have been detected by weather radar.
3. The aircraft was affected by a short period of moderate to severe turbulence associated with cloud.
4. A number of passengers had failed to follow the recommended usage of the seatbelts.