## **Aviation Safety Investigation Report 198700750**

Piper PA23 Aztec

**7 October 1987** 

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198700750 Occurrence Type: Accident

**Location:** Kimba SA

**Date:** 7 October 1987 **Time:** 831

Highest Injury Level: Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

**Aircraft Details:** Piper PA23 Aztec

**Registration:** VH-WGN **Serial Number:** 27-7305233

**Operation Type:** Charter (Commercial)

Damage Level: Substantial
Departure Point: Cleve SA
Departure Time: 0817
Destination: Kimba SA

**Approved for Release:** December 16th 1987

## **Circumstances:**

After landing, as the aircraft turned left into the taxiway, the left maingear collapsed. Inspection revealed that the drag link centrebolt had failed. Examination of the bolt revealed that it had failed due to fatigue, which had initiated from pit corrosion along the shank of the bolt. It also displayed signs of in-service wear which possibly contributed to the failure. This aircraft reportedly operated from rough, uneven dirt strips on a regular basis.