1

Aviation Safety Investigation Report 198502562

Piper PA28-R180

08 November 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198502562 Occurrence Type: Accident

Location: Cessnock NSW

Date: 08 November 1985 **Time:** 1100 aprx

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Piper PA28-R180

Registration: VH-CHI

Serial Number:

Operation Type: Aerial Work (Solo Training)

Damage Level: Substantial
Departure Point: Cessnock NSW
Departure Time: 1100 aprx
Destination: Cessnock NSW

Approved for Release: 21st February, 1986

Circumstances:

The pilot had successfully carried out a series of seven circuits with touch and go landings. He subsequently advised that he had been experiencing difficulties in maintaining accurate height and tracking on the downwind leg, and while concentrating on these points on the eighth circuit he forgot to lower the landing gear. As he flared the aircraft, he heard a radio message instructing him to go around. Full power was immediately applied, but the aircraft contacted the runway and skidded to a halt. The pilot had been relying on a memorised check list and, when distracted, performed only some of the checks required.