

**Aviation Safety Investigation Report
198901551**

Piper PA28-161

26 August 1989

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198901551
Location: Moorabbin VIC
Date: 26 August 1989
Highest Injury Level: Nil
Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	2	2
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	2

Aircraft Details: Piper PA28-161
Registration: VH-CBF
Serial Number: 28-7716276
Operation Type: Aerial work
Damage Level: Substantial
Departure Point: Moorabbin VIC
Departure Time: 1700
Destination: Moorabbin VIC

Approved for Release: 2nd April 1990

Circumstances:

The student made a normal landing but as the aircraft slowed, the instructor noted the right wing was sinking and he assumed control of the aircraft. He held the wing up as long as he could and kept the aircraft straight without braking. The aircraft slowly veered to the right and came to rest off the sealed runway surface. The right hand landing gear wheel assembly had separated from the aircraft about thirteen metres after touchdown, with the result that the right hand flap, torque tube, aileron and stub of the landing gear cylinder were damaged by abrasion with the runway surface. The right hand landing gear strut had separated from the cylinder due to one of the two torque link securing lugs failing from fatigue, and the torque link retaining bolt failed due to overload. The main landing gear cylinder torque link lugs are subject to a visual inspection every 100 hours by aircraft maintenance engineers, but there is no existing requirement to inspect the strut torque link lugs.

Significant Factors:

The following factors were considered relevant to the development of the accident

1. The torque link lugs failed because of fatigue.

Reccomendations:

It is recommended that the Civil Aviation Authority amend AD/PA-28/50 to incorporate dye penetrant inspection of the main landing gear torque link upper and lower mounting lugs.