Aviation Safety Investigation Report 199800188

Piper Aircraft Corp Cherokee Six

22 January 1998

Aviation Safety Investigation Report 199800188

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199800188

Occurrence Number: 199800188 Occurrence Type: Accident

Location: 86km ENE Roma, Aerodrome

State: QLD Inv Category: 4

Date: Thursday 22 January 1998

Time: 1615 hours **Time Zone** EST

Highest Injury Level: Serious

Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	1	1	0	2
Ground	0	0	0	0	0
Passenger	0	0	1	0	1
Total	0	1	2	0	3

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-32-300

Aircraft Registration: VH-JQL Serial Number: 32-7140017

Type of Operation: Commercial Aerial Agriculture/Baiting

Damage to Aircraft: Destroyed

Departure Point: Nullin Station Qld

Departure Time:

Destination: Nullin Station Old

Crew Details:

	Hours on				
Role	Class of Licence	Type Ho	urs Total		
Pilot-In-Command	Commercial	200.0	7500		

Approved for Release: Monday, February 2, 1998

The pilot reported that the engine faltered briefly when he applied full power while rolling out of a procedure turn during an aerial seeding operation. He then deliberately stalled the aircraft into the tops of trees when it was clear that it was losing performance. The aircraft rolled right and struck the ground in a nose down, inverted attitude. The pilot and station manager occupied the front seats, the seed dispatcher was tethered by a lanyard in the rear cabin from which the seats had been removed. All three occupants were taken to hospital, two with minor and one with serious injuries.

The aircraft carried an emergency locator transmitter (ELT) which was fixed to structure in the rear fuselage. The ELT worked automatically, alerting AusSAR to the accident.

Onsite photographs indicated that the engine was producing high power when the propeller struck tree trunks. The flight conditions were extreme; 43 degrees C, moderate turbulence and a density altitude of approximately 5,200 ft.