

**Aviation Safety Investigation Report  
199801668**

**Embraer-Empresa Brasileira de  
Aeronautica  
Piper Chieftain**

**11 May 1998**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199801668      **Occurrence Type:** Accident  
**Location:** Scone, (ALA)  
**State:** NSW      **Inv Category:** 4  
**Date:** Monday 11 May 1998  
**Time:** 1100 hours      **Time Zone:** EST  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Embraer-Empresa Brasileira de Aeronautica  
**Aircraft Model:** EMB-820-C  
**Aircraft Registration:** VH-HVA      **Serial Number:** 820C-045  
**Type of Operation:** Air Transport Domestic Low Capacity Passenger  
**Damage to Aircraft:** Substantial  
**Departure Point:** Scone NSW  
**Departure Time:** 1100 EST  
**Destination:** Gunnedah NSW

**Crew Details:**

<b>Role</b>	<b>Class of Licence</b>	<b>Hours on Type</b>	<b>Hours Total</b>
Pilot-In-Command	Commercial	1000.0	2400

**Approved for Release:** Thursday, July 2, 1998

After taking off from Scone, the pilot of an Embraer 820C aircraft reported that when retracting the landing gear, the landing gear selector failed to return to the neutral position, and the gear unsafe light remained on. The emergency checklist was actioned and the emergency hand pump was used by the pilot to extend the landing gear, however, the nose gear failed to lock down. The pilot requested emergency services to be in attendance prior to returning for a landing. When the aircraft subsequently landed, the nose gear collapsed during the landing roll. The pilot and passenger vacated the aircraft without injury.

An investigation revealed that the right engine driven hydraulic pump was leaking from a loose suction line fitting, and that most of the hydraulic fluid had been lost overboard. Inspection of the hydraulic hand pump found contamination of the check valve. This was probably enough to hold the valve off its seat so that insufficient pressure was available to lock the nose gear in the down position.



Further investigation determined that the right engine had been changed prior to the accident flight. As the engine had been supplied without a hydraulic pump, a serviceable pump was fitted. During engine ground running, the right hydraulic pump failed to pressurise the system and it was assumed that, because the left and right engines rotate in opposite directions, the pump was configured for left engine rotation. On completion of the engine run, the hydraulic pump lines were reconfigured for correct rotation. A very short engine run confirmed that the pump pressurised the system and that no leaks were apparent. However, the suction line had not been properly tightened, which was not detected. Sometime later, at about the time the aircraft departed, hydraulic fluid commenced to leak from the loose suction line fitting.

It is likely that whilst the pump was operating in the reverse rotation mode during the first engine run, the reversed hydraulic flow disturbed any sediment that was in the hydraulic system. The contamination then found its way into the hand pump when it was operated by the pilot during the emergency extension of the landing gear.

