

**Aviation Safety Investigation Report
199700172**

**Cessna Aircraft Company
Titan**

16 January 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199700172	Occurrence Type: Incident
Location: Renmark, Aerodrome	
State: SA	Inv Category: 4
Date: Thursday 16 January 1997	
Time: 1759 hours	Time Zone: ESuT
Highest Injury Level: None	

Aircraft Manufacturer: Cessna Aircraft Company	
Aircraft Model: 404	
Aircraft Registration: VH-UOP	Serial Number: 4040636
Type of Operation: Air Transport Passenger Scheduled	
Damage to Aircraft: Nil	
Departure Point: Renmark SA	
Departure Time: 1859 ESuT	
Destination: Adelaide SA	

Approved for Release: Thursday, March 20, 1997

Shortly after the Cessna Titan had departed from Renmark the pilot advised he had problems with the elevator trim control and would be returning to land. Although the pilot said that the controls felt heavy he was able to carry out a satisfactory landing.

An initial inspection found the right elevator trim tab was not responding to trim wheel movement.

Detailed maintenance inspection disclosed that the right elevator trim actuator drive sprocket was sheared. The sprocket shaft support bearing had worn such that the bearing was severely elongated. It was determined that if the drive cables were properly tensioned this wear would not be noticed during a visual inspection.

The operator conducted a fleet check of the actuators which are used in the aileron, rudder and elevator control systems of the Titan as well as other Cessna aircraft. The fleet check disclosed one other severely worn actuator.

The company maintenance system manual (MSM) has a requirement for a visual inspection to be carried out every 100 hours. The MSM did not specify an overhaul period. However it was found that the aircraft manufacturer has a requirement for these actuators to be overhauled every 1,000 hours. The operator had never overhauled these actuators because the MSM did not reflect the manufacturer's requirement.

It is not known why the manufacturer's requirement had not been transcribed into the MSM. Approval of the content of the MSM is twofold. Firstly the operator has the manual compiled and internally assessed and approved. Secondly, the manual is submitted to the Airworthiness Branch of the Civil Aviation Safety Authority for formal approval by the Authority. Both assessment sequences failed to detect the omission.

The operator and the Authority have agreed on program to phase introduction of the overhaul period into the fleet. They have also conducted an audit of the operator's MSM to ensure that the manual accurately reflects the manufacturer's requirements.

The Authority advised that an assessment of other operators of Cessna twin engined aircraft fitted with these actuators have found some who were not aware of and not complying with the manufacturer's overhaul requirement.

