Aviation Safety Investigation Report 199701113

Air Tractor Inc AT-301

09 April 1997

Aviation Safety Investigation Report 199701113

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199701113 Occurrence Type: Incident

Location: 4km N Ayr, Aerodrome

State: QLD Inv Category: 4

Date: Wednesday 09 April 1997

Time: 0730 hours **Time Zone** EST

Highest Injury Level: None

Aircraft Manufacturer: Air Tractor Inc

Aircraft Model: AT-301

Aircraft Registration: VH-FEI Serial Number: 301-0574

Type of Operation: Commercial Aerial Agriculture - Other

Damage to Aircraft:MinorDeparture Point:Ayr QLDDeparture Time:0700 ESTDestination:Ayr QLD

Crew Details:

Role Class of Licence Type Hours Total
Pilot-In-Command Commercial 122.0 6500

Approved for Release: Friday, April 11, 1997

This was the first occasion on which the pilot had sprayed the sugar cane paddock. A briefing and an area map were obtained from the property owner. The pilot conducted a power line inspection and found three lines, all that had been brought to his attention. During the first spray run he noticed sparks at the propeller as an unseen set of three wires was cut. He returned to the takeoff point and found that only the propeller had been damaged. The wires struck had not been seen at all. The relevant poles were hidden in trees on each side of the paddock.