**Aviation Safety Investigation Report 199701167** 

**Piper Aircraft Corp Pawnee Brave** 

**04 April 1997** 

## Aviation Safety Investigation Report 199701167

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

## **Aviation Safety Investigation Report**

199701167

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199701167 Occurrence Type: Accident

**Location:** 19km NNE Moree, Aerodrome

State: **Inv Category:** 

Date: Friday 04 April 1997

Time: 1330 hours Time Zone **EST** 

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-36-375

VH-JJO Aircraft Registration: **Serial Number:** 36-7802072

**Type of Operation:** Aerial Agriculture - Other Commercial

**Damage to Aircraft:** Substantial

**Departure Point:** Sappa airstrip, NSW

1330 EST **Departure Time:** 

**Destination:** Sappa airstrip NSW

**Crew Details:** 

	Hours on		
Role	Class of Licence	Type Ho	ours Total
Pilot-In-Command	Senior Commercial	2519.0	12562

**Approved for Release:** Tuesday, September 16, 1997

The aircraft was involved in a cotton spraying operation. The pilot reported that on the tenth takeoff the aircraft failed to accelerate to normal climb speed, only reaching a height of about 15 ft. He dumped the load but was unable to prevent the aircraft descending into the cotton crop. Although the aircraft was substantially damaged the pilot was uninjured.

The engine subsequently performed normally during a test run. The pilot reported that he remembered strong 'willy willy' activity in the area immediately after the accident. He concluded it was likely that the takeoff performance of the aircraft had been adversely affected by a wind gust at liftoff.