Aviation Safety Investigation Report 199701686

Airbus A320 Airbus A330-300

25 May 1997

Aviation Safety Investigation Report 199701686

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199701686

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199701686 Occurrence Type: Incident

Location: 172km NW Brisbane, Aerodrome

State: QLD Inv Category: 4

Date: Sunday 25 May 1997

Time: 0800 hours Time Zone EST

Highest Injury Level: None

Aircraft Airbus

Manufacturer:

Aircraft Model: A330-300

Aircraft Registration: 9MMKH Serial

Number:

Type of Operation: Air Transport High Capacity International Passenger

Scheduled

Damage to Aircraft: Nil

Departure Point: Kuala Lumpur/Int. Malaysia

Departure Time:

Destination: Brisbane QLD

Aircraft Airbus

Manufacturer:

Aircraft Model: A320-211

Aircraft Registration: VH-HYJ Serial 142

Number:

Type of Operation: Air Transport Domestic High Capacity Passenger

Scheduled

Damage to Aircraft: Nil

Departure Point:Cairns QLDDeparture Time:0815 ESTDestination:Brisbane QLD

Approved for Release: Thursday, August 7, 1997

Circumstances

MAS135 and VH-HYJ were third and forth in a six aircraft sequence. They were both inbound to Brisbane from the north-west, with VH-HYJ behind MAS135 and operating at a higher speed. As the sequence progresses, the controller was late in detecting the reducing separation between the two aircraft. HUJ was turned away from MAS135 but not sufficiently early to prevent lateral separation reducing to 4 NM. At the time, vertical separation was 500 ft.

The controller involved was undergoing a routine periodic performance check. In the lead-up to the incident, the check officer was unplugged from the position, discussing other aspects of the traffic sequence with the terminal area cell. Examination of the recorded radar and audio data leading up to the incident revealed that the controller was over-reliant on monitoring radar separation at the expense of positive separation assurance. This situation was probably exacerbated by his lack of recent experience on the sector during a busy period.