**Aviation Safety Investigation Report 199702602** 

Kawasaki Heavy Industries Kawasaki KH4

13 August 1997

## Aviation Safety Investigation Report 199702602

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199702602 Occurrence Type: Accident

**Location:** Kings Canyon, (VEC)

State: QLD Inv Category: 4

**Date:** Wednesday 13 August 1997

**Time:** 1330 hours **Time Zone** EST

Highest Injury Level: Minor

**Injuries:** 

	Fatal	Serious	Minor	None	Total
Crew	0	0	0	1	1
Ground	0	0	0	0	0
Passenger	0	0	1	2	3
Total	0	0	1	3	4

Aircraft Manufacturer: Kawasaki Heavy Industries

**Aircraft Model:** 47G3B-KH4

Aircraft Registration: VH-JAJ Serial Number: 2188

**Type of Operation:** Charter Passenger

**Damage to Aircraft:** Substantial

**Departure Point:** Kings Canyon QLD

**Departure Time:** 

**Destination:** Kings Canyon QLD

**Crew Details:** 

	Hours on			
Role	<b>Class of Licence</b>	<b>Type Hours Total</b>		
Pilot-In-Command		726		

**Approved for Release:** Thursday, August 21, 1997

## Circumstances

The pilot reported that the helicopter landed heavily in a carpark, after the engine lost power during takeoff. On lift-off, engine indications were normal with 28-29 inches boost while in the hover. As the helicopter accelerated, the pilot felt a deterioration in performance and observed that the boost had fallen to 15-18 inches. During the subsequent landing, the helicopter's main rotor blades struck a tree and both landing skids were bent. The helicopter remained upright. Post flight examination found that the turbo charger had failed.