

**Aviation Safety Investigation Report  
199703441**

**Robinson Helicopter Co  
R22**

**20 October 1997**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199703441 **Occurrence Type:** Accident  
**Location:** 165km WNW Newman, Aerodrome  
**State:** WA **Inv Category:** 4  
**Date:** Monday 20 October 1997  
**Time:** 1600 hours **Time Zone:** WST  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Robinson Helicopter Co  
**Aircraft Model:** R22 BETA  
**Aircraft Registration:** VH-JKN **Serial Number:** 1023  
**Type of Operation:** Commercial Other  
**Damage to Aircraft:** Destroyed  
**Departure Point:** Talawana WA  
**Departure Time:**  
**Destination:** Talawana WA

**Crew Details:**

Role	Class of Licence	Hours on	
		Type	Hours Total
Pilot-In-Command	Commercial	495.0	600

**Approved for Release:** Friday, November 21, 1997

The helicopter had just finished being used to survey cattle and was returning for a landing. The pilot reported that the engine governor was turned on and that during a steep turn downwind, he allowed the helicopter's airspeed to decrease to approximately 20 kts. As he lowered the helicopter's nose to accelerate downwind, the Low Rotor RPM warning horn sounded indicating that the main rotor RPM had decreased below 96%. The pilot reported that he immediately lowered the collective, fully opened the throttle and further lowered the helicopter's nose to recover airspeed. As the helicopter approached the ground, he selected a decelerative attitude, a manoeuvre that would normally recover some main rotor RPM. However, in this case, the main rotor RPM did not recover. When the helicopter had descended to approximately 3 ft AGL with an airspeed of approximately 55 kts, the pilot placed it in a sideways quick-stop manoeuvre. This was done to decrease the helicopter's air and ground speed before it contacted the ground. The pilot reported that he then levelled the helicopter before running it onto a sand ridge. Despite these actions, the Low Rotor RPM warning horn continued to sound throughout the descent and landing. After sliding along the ground for approximately 20 ft, the helicopter somersaulted.

After the dust had settled following the crash, the pilot reported that he checked the welfare of his passenger and then checked the engine. The pilot reported that the engine exhaust was cool enough to hold and that the rocker cover was only warm to touch.

