**Aviation Safety Investigation Report** 199703704

Piper Aircraft Corp Navajo

**12 November 1997** 

## Aviation Safety Investigation Report 199703704

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

## **Aviation Safety Investigation Report**

199703704

Occurrence Number: 199703704 Occurrence Type: Accident

**Location:** 6km NNE Maitland, (ALA)

State: NSW Inv Category: 4

**Date:** Wednesday 12 November 1997

Time: 1730 hours Time Zone ESuT

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

**Aircraft Model:** PA-31

Aircraft Registration: VH-WAL Serial Number: 31-7300943

**Type of Operation:** Charter Cargo

Damage to Aircraft:SubstantialDeparture Point:Scone NSWDeparture Time:1706 ESuT

**Destination:** Maitland ALA NSW

**Crew Details:** 

Role Class of Licence Type Hours Total

Pilot-In-Command ATPL 300.0 1900

**Approved for Release:** Monday, July 6, 1998

The pilot was conducting a scheduled freight run and earlier that day had refuelled the aircraft and departed Bankstown with full main tanks (401 litres) and 160 litres in the auxiliary tanks. The accident flight was on the Scone to Maitland sector, and the pilot reported that when departing Scone, the aircraft had about 108 kilograms of freight and 430 litres of fuel .

The pilot reported that while on descent and at about five miles from Maitland, the right engine RPM began to fluctuate with an accompanied increase in vibration. The pilot, thinking that it was a malfunction of the propeller governor, reported that he shut down the right engine and selected the right propeller to feather.

The pilot observed that the right propeller was still windmilling, the indicated airspeed was decreasing and that the aircraft was unable to maintain height, so he elected to land in a nearby field. He closed the left throttle and selected the landing gear down. The landing gear collapsed on touchdown as there had been insufficient time for it to extend and lock. The aircraft slid for about 120 metres.

Investigation of the fuel system indicated that the auxiliary tanks were empty while the main tanks each contained about 140 litres. The cockpit fuel selectors indicated that the main fuel tanks were selected.

Investigation of the engines and their systems, including the propellers and governors, could not determine the reason for the reported propeller malfunction or the inability of the aircraft to maintain height.