

**Aviation Safety Investigation Report
199704267**

**Cessna Aircraft Company
A185E**

29 December 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199704267 **Occurrence Type:** Accident
Location: Peterborough, (ALA)
State: VIC **Inv Category:** 4
Date: Monday 29 December 1997
Time: 1014 hours **Time Zone** ESuT
Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company
Aircraft Model: A185E
Aircraft Registration: VH-FLU **Serial Number:** 1851315
Type of Operation: Charter Passenger
Damage to Aircraft: Substantial
Departure Point: Moorabbin Vic.
Departure Time: 0917 ESuT
Destination: Peterborough Vic.

Crew Details:

Role	Class of Licence	Hours on	
		Type	Hours Total
Pilot-In-Command	Commercial	1142.0	3362

Approved for Release: Monday, January 12, 1998

The pilot was flying a Cessna 185 aircraft on a VFR charter flight from Moorabbin to Peterborough with 2 passengers. On arrival at Peterborough he overflew the strip and estimated the wind to be from 220 degrees at 5 to 7 kts. The strip has an uphill gradient to the east, and, even though this would result in a slight tailwind from the right quarter for the landing, the pilot elected to accept this and make use of the uphill gradient.

The landing was reported to have been smooth and light and was accomplished with a trickle of power and full flap (4 stages). During the roll out the aircraft diverged slightly left and then made a rapid and increasing swing to the right. Application of rudder and brake was not able to stop the developing ground loop. The aircraft left the mown strip with the group loop tightening until the left main landing gear collapsed. The aircraft came to rest pointing back down the strip towards the touchdown point.

After shutting down the engine the pilot and passengers evacuated without assistance or injury.

The pilot considered that he should have used a different technique when landing. A powered approach with 2 stages of flap, raising the flaps as soon as possible after landing, and using power to ensure adequate rudder authority during roll out would have result in control of the aircraft being maintained.

