Aviation Safety Investigation Report 199600390

Amateur Built Aircraft Rutan long-ez

06 February 1996

Aviation Safety Investigation Report 199600390

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199600390 Occurrence Type: Incident

Location: Canberra, Aerodrome

State: ACT Inv Category: 4

Date: Tuesday 06 February 1996

Time: 1242 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Amateur Built Aircraft

Aircraft Model: LONG-EZ

Aircraft Registration: VH-LEP Serial Number: N177

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Minor

Departure Point: Canberra ACT

Departure Time:

Destination: Canberra ACT

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours Total	
Pilot-In-Command	Private	78.0	360

Approved for Release: Tuesday, March 19, 1996

The pilot reported that the approach which ATC required was very steep and slow. Consequently, she forgot to lower the nose gear and the aircraft landed on the main gear only.

The pilot had flown only two flights in the past three months. She was distracted with the unusually close approach and workload in a relatively high traffic area. It was discovered after that the gear warning horn and light were unserviceable.