**Aviation Safety Investigation Report 199603263** 

Robinson Helicopter Co R22

12 October 1996

## Aviation Safety Investigation Report 199603263

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199603263 Occurrence Type: Accident

**Location:** 19km SE Chatsworth, (ALA)

State: QLD Inv Category: 4

**Date:** Saturday 12 October 1996

**Time:** 0930 hours **Time Zone** EST

**Highest Injury Level:** Minor

**Injuries:** 

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	1	0	1
Total	0	0	2	0	2

**Aircraft Manufacturer:** Robinson Helicopter Co

**Aircraft Model:** R22 BETA

Aircraft Registration: VH-BFG Serial Number: 2493

**Type of Operation:** Non-commercial Aerial Mustering

**Damage to Aircraft:** Destroyed

**Departure Point:** Chatsworth Station QLD

**Departure Time:** 0900 EST

**Destination:** Chatsworth Station QLD

**Crew Details:** 

	Hours on		
Role	Class of Licence	Type Hou	ırs Total
Pilot-In-Command	Private	850.0	850

**Approved for Release:** Tuesday, March 25, 1997

The pilot reported that he had descended with the intention of moving a mob of cattle when some ran under the helicopter. He turned to follow the cattle but then realised that he was travelling downwind. Power to maintain height was not adequate and the main rotor was overpitched. As a result, the helicopter struck the ground hard with a ground speed of about 20 kts. The pilot assessed the wind as south-easterly at 15 to 20 kt.

Prior to recovery of the helicopter, the owner checked the engine and was satisfied that it was capable of normal operation.

The fixed emergency locator transmitter was activated, but was not used or required for the rescue. The occupants walked to a nearby hill and used a citizen band radio to contact a truck which took them to a local mine.