Aviation Safety Investigation Report 199603314

Robinson Helicopter Co R22

15 October 1996

Aviation Safety Investigation Report 199603314

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199603314 Occurrence Type: Accident

Location: 28km NNW Brunchilly, (ALA)

State: NT Inv Category: 4

Date: Tuesday 15 October 1996

Time: 0945 hours **Time Zone** CST

Highest Injury Level: None

Aircraft Manufacturer: Robinson Helicopter Co

Aircraft Model: R22 BETA

Aircraft Registration: VH-LKS Serial Number: 1163

Type of Operation: Commercial Aerial Mustering

Damage to Aircraft: Substantial

Departure Point: Brunchilly Station NT

Departure Time: 0935 CST

Destination: Brunchilly Station NT

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours Total	
Pilot-In-Command	Commercial	500.0	500

Approved for Release: Thursday, October 17, 1996

The pilot was trying to muster a herd of about 12 head of cattle away from a bore to yards a couple of miles away. The cattle persisted in trying to return to the bore for water. The pilot hoped to overcome the cattle's reluctance to move by flaring the helicopter low and close to the herd. He flared down to about 5 ft and 5 kts across the herd's direction of movement and about 5 metres from the lead animal. During the flare, one bullock darted from the herd towards the right rear of the helicopter. The pilot felt a slight thump through the airframe. He immediately increased power to move on but the helicopter yawed right rapidly. By the time the pilot managed to close the throttle, the helicopter had turned through 360 degrees. Once the throttle was closed the rate of yaw diminished and the helicopter rapidly settled to the ground; it contacted first with the right skid which broke. Then, as the helicopter rolled onto its right side, the main rotors were destroyed by ground impact.

When the bullock darted towards the rear of the helicopter, it impacted the spinning tail rotor with its back and broke off both of the tail rotor blades.