

**Aviation Safety Investigation Report
199603690**

**Beech Aircraft Corp
Super King Air**

10 November 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199603690 **Occurrence Type:** Incident
Location: 28km E Wagga Wagga, VOR
State: NSW **Inv Category:** 4
Date: Sunday 10 November 1996
Time: 1700 hours **Time Zone** ESuT
Highest Injury Level: None

Aircraft Manufacturer: Beech Aircraft Corp
Aircraft Model: 200
Aircraft Registration: VH-YNE **Serial Number:** BB-605
Type of Operation: Charter Passenger
Damage to Aircraft: Nil
Departure Point: Adelaide SA
Departure Time: 1520 ESuT
Destination: Canberra ACT

Crew Details:

Role	Class of Licence	Hours on Type	Hours Total
Pilot-In-Command	ATPL	400.0	7750

Approved for Release: Monday, June 30, 1997

The pilot reported that the Beech 200 King Air was passing through FL230, on descent from FL270, when he heard a loud bang. He advised ATC that both he and the sole passenger had donned oxygen masks as a result of a sudden loss of cabin pressurisation.

A post flight inspection of the aircraft found that the rear entrance upper latch hook had failed, permitting a loss of cabin pressurisation. The hook is an item with a replacement life of 12,000 flight hours. The failed door latch hook was reported to have completed 4704.5 hours, and 4295 pressurisation cycles, since new.

Failure analysis of the door latch hook found that the failure was caused by the growth of fatigue cracking, initiating from the inner radius of the hook. Subsequent crack extension was by a stress corrosion mechanism.

Several factors were considered to have contributed to the failure of the hook well before the expiry of its designated safe life, including:

- a surface irregularity created during machining of the hook;

- fatigue crack initiation from that machining irregularity;
- lack of corrosion protection of the door latch hook; and
- stress corrosion from prolonged exposure to a corrosive environment.

SAFETY ACTION

The Bureau of Air Safety Investigation issued Safety Advisory Notice 970071 which drew the attention of the Civil Aviation Safety Authority to the fatigue failure of the hook.

